



***Federal Railroad Administration  
Office of Safety  
Headquarters Assigned  
Accident Investigation Report  
HQ-2006-100***

***Union Pacific  
Marlin, TX  
December 15, 2006***

***Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.***

1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP ]			1a. Alphabetic Code UP			1b. Railroad Accident/Incident No. 1206FW018			
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A			2b. Railroad Accident/Incident N/A			
3. Name of Railroad Responsible for Track Maintenance: Union Pacific RR Co. [UP ]			3a. Alphabetic Code UP			3b. Railroad Accident/Incident No. 1206FW018			
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month   Day   Year 12   15   2006			6. Time of Accident/Incident 07:30: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM			
7. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision			4. Side collision 5. Raking collision 6. Broken Train collision			
			7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction			10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts			
			13. Other (describe in narrative)			01			
8. Cars Carrying HAZMAT 0		9. HAZMAT Cars Damaged/Derailed N/A		10. Cars Releasing HAZMAT N/A		11. People Evacuated 0		12. Division Fort Worth	
13. Nearest City/Town Marlin			14. Milepost (to nearest tenth) 131.2		15. State Abbr Code N/A   TX		16. County FALLS		
17. Temperature (F) (specify if minus) 66 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1			
21. Track Name/Number Single Main Track			22. FRA Track Code Class (1-9, X) 4		23. Annual Track Density (gross tons in millions) 26		24. Time Table Direction Code 1. North 3. East 1		
<b>OPERATING TRAIN #1</b>									
25. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars			
			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car			A. Spec. MoW Equip. Code 1		26. Was Equipment Attended? 1. Yes 2. No 1	
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 50 MPH   R			30. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking			g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits			
29. Trailing Tons (gross tonnage, excluding power units) 4834			30. Method(s) of Operation (enter code(s) that apply) m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s)			30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0			
31. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded (yes/no)	32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.				
(1) First involved (derailed, struck, etc)		N/A	6	yes	Alcohol		Drugs		
(2) Causing (if mechanical cause reported)		0	0	N/A	N/A		N/A		
33. Was this consist transporting passengers? (Y/N)					N				
34. Locomotive Units		a. Head End	b. Mid Train	c. Rear End	35. Cars		a. Freight	b. Pass.	
		d. Manual	e. Remote				c. Freight	d. Pass.	
(1) Total in Train		2	0	0	(1) Total in Equipment Consist		36	0	
(2) Total Derailed		0	0	0	(2) Total Derailed		31	0	
		0	0	0			0	0	
		0	0	0			0	0	
36. Equipment Damage This Consist		1680119		37. Track, Signal, Way, & Structure Damage		242360		38. Primary Cause Code T101	39. Contributing Cause Code N/A
Number of Crew Members					Length of Time on Duty				
40. Engineer/Operators N/A		41. Firemen 0	42. Conductors 1	43. Brakemen 0	44. Engineer/Operator Hrs 2 Mi 30			45. Conductor Hrs 2 Mi 30	
Casualties to:		46. Railroad Employees	47. Train Passengers	48. Other	49. EOT Device? 1. Yes 2. No 1			50. Was EOT Device Properly Armed? 1. Yes 2. No 1	
Fatal		0	0	0	51. Caboose Occupied by Crew? 1. Yes 2. No			N/A	
Nonfatal		N/A	0	0					
<b>OPERATING TRAIN #2</b>									
52. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars			
			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car			A. Spec. MoW Equip. Code N/A		53. Was Equipment Attended? 1. Yes 2. No N/A	
54. Train Number/Symbol N/A									
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH   N/A		57. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control			g. Automatic block h. Current of traffic m. Special instructions n. Other than main track			57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

56. Trailing Tons (gross tonnage, excluding power units) 0		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A					
58. Principal Car/Unit (1) First involved (derailed, struck, etc) 0		a. Initial and Number 0		b. Position in Train 0		c. Loaded(yes/no) N/A		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol: N/A Drugs: N/A					
(2) Causing (if mechanical cause reported) 0		0		N/A		60. Was this consist transporting passengers? (Y/N) N/A							
61. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote		62. Cars		Loade a. Freight b. Pass. c. Freight d. Pass. e. Caboose			
(1) Total in Train 0		0		0		0		(1) Total in Equipment Consist 0		0			
(2) Total Derailed 0		0		0		0		(2) Total Derailed 0		0			
63. Equipment Damage This Consist 0		64. Track, Signal, Way, & Structure Damage 0		65. Primary Cause Code N/A		66. Contributing Cause Code N/A		Number of Crew Members		Length of Time on Duty			
67. Engineer/Operators 0		68. Firemen 0		69. Conductors 0		70. Brakemen 0		71. Engineer/Operator Hrs 0 Mi 0		72. Conductor Hrs 0 Mi 0			
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device? 1. Yes 2. No N/A		77. Was EOT Device Properly Armed? 1. Yes 2. No N/A			
Fatal 0		0		0		0		78. Caboose Occupied by Crew? 1. Yes 2. No		N/A			
Nonfatal 0		0		0		0							
Highway User Involved						Rail Equipment Involved							
79. Type C. Truck-Trailer. F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative) Code N/A		80. Vehicle Speed (est. MPH at impact) N/A		81. Direction geographical 1. North 2. South 3. East 4. West Code N/A		82. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped Code N/A		83. Equipment 1. Train(units pulling) 2. Train(units pushing) 3. Train (standing) 4. Car(s)(moving) 5. Car(s)(standing) 6. Light Loco(s) (moving) 7. Light(s) (standing) 8. Other (specify in narrative) Code N/A		84. Position of Car Unit in Train N/A		85. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User Code N/A	
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither Code N/A						86b. Was there a hazardous materials release by 1. Highway User 2. Rail Equipment 3. Both 4. Neither Code N/A							
86c. State here the name and quantity of the hazardous materials released, if any. N/A													
87. Type of Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS Code(s) N/A		4. Wig Wags 5. Hwy. traffic signals 6. Audible N/A		7. Crossbucks 8. Stop signs 9. Watchman N/A		10. Flagged by crew 11. Other (spec. in narr.) 12. None N/A		88. Signaled Crossing Warning (See instructions for codes) Code N/A		89. Whistle Ban 1. Yes 2. No 3. Unknown Code N/A			
90. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach Code N/A		91. Crossing Warning Interconnected with Highway Signals 1. Yes 2. No 3. Unknown Code N/A		92. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown Code N/A		93. Driver's Age 0		94. Driver's Gender 1. Male 2. Female Code N/A		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown Code N/A		96. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop 4. Stopped on Crossing 5. Other (specify in narrative) Code N/A	
97. Driver Passed Standing Highway Vehicle 1. Yes 2. No 3. Unknown Code N/A		98. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed Code N/A		101. Casualties to Highway-Rail Crossing Users Killed 0		Injured 0		102. Highway Vehicle Property Damage (est. dollar damage) 0		100. Was Driver in the Vehicle? 1. Yes 2. No Code N/A		103. Total Number of Highway-Rail Crossing Users (include driver) 0	
104. Locomotive Auxiliary Lights? 1. Yes 2. No Code N/A		105. Locomotive Auxiliary Lights Operational? 1. Yes 2. No Code N/A		106. Locomotive Headlight Illuminated? 1. Yes 2. No Code N/A		107. Locomotive Audible Warning Sounded? 1. Yes 2. No Code N/A							

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.  
HQ-100-  
2006.jpg

U.S. Department of Transportation  
Federal Railroad Administration

**FRA FACTUAL RAILROAD ACCIDENT REPORT**

FRA File # HQ-2006-100

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

UP 7542  
UP 7550  
CMEX 140018  
SDWX 010140  
CMEX 140687  
CMEX 110675  
CMEX 110869  
CMEX 110850  
CMEX 110647  
CMEX 140047  
CMEX 110711  
CMEX 110576  
DSTX 059028  
CMEX 011475  
CMEX 110611  
SDWX 010021  
CMEX 110648  
CMEX 110633  
CMEX 110832  
CMEX 130100  
CMEX 110610  
CMEX 110636  
CMEX 110851  
CMEX 110846  
CMEX 110856  
CMEX 110683  
CMEX 140145  
CMEX 140142  
CMEX 140083  
CMEX 110715  
CMEX 110869  
CMEX 110654  
CMEX 130163  
CMEX 130255  
CMEX 011499  
CMEX 110841

CMEX 110574  
CMEX 110608  
CMEX 130118  
CMEX 110653  
CMEX 110651  
CMEX 130134

County Rd. 202

POD

#### 109. SYNOPSIS OF THE ACCIDENT

On December 15, 2006, at 7:30 p.m. (CST), a northbound UP freight train, RDTFWC-15, derailed at mile post 131.2, on the main track. This location is approximately 5 mi. south of Marlin, Texas on the Fort Worth Sub-division of the Fort Worth Service Unit.

The fourth thru thirty-fourth freight cars of the forty car train behind two locomotives derailed. The thirty one cars that derailed were all hopper cars loaded with dry cement. There were no casualties, no release hazardous materials, nor were there any evacuations in the rural area. Monetary damages are estimated to be \$1,922,479. Monetary cost of lading totaled \$183,063. Total costs amounted to \$2,105,542.

The temperature, visibility, and weather at 7:30 p.m., On December 15, 2006 was 66 degrees Fahrenheit, dark, with clear skies.

The cause of the derailment was irregular cross level at joints. These joints were located just south of the road crossing at milepost 131.23 . Measurements taken during the post accident investigation confirmed this cause. The track in this area is CWR and wood ties, but repair rail had been cut in at a previous date, allowing this condition to exist.

#### 110. NARRATIVE

The crew of train RDTFWC-15, was a two person train crew and consisted of a locomotive engineer and conductor. The crew went on duty at 5 p.m.(CST), on December 15, 2006 at Hearne, Texas and got on RDTFWC-15 at Valley Jct. Both crew members had received more than the statutory off duty period prior to reporting for duty.

The RDTFWC-15, an unit powdered cement train, consisted of two locomotives, 36 loaded and four empty hopper cars. The train was 1832 feet in length and was pulling 4834 trailing tons.

As the train approached the derailment area from the south, the train was traveling 50 mph (recorded).The maximum authorized speed for freight trains is 60 mph, as designated in the current Union Pacific Railroad Timetable No. 2. The engineer was seated on the seat provided near the control stand on the east side of the lead and controlling locomotive. The conductor of the train was seated on the seat provided on the west side and directly across from the locomotive engineer. The engineer stated that he felt a rough spot, put the engine in dynamic braking mode and the train went into emergency.

In this area of the railroad, the track is 119 lb. CWR and installed in 1965. The track is tangent and the grade is level.

The railroad timetable direction of train symbol RDTFWC-15, was north. The geographic direction was northwest. Timetable directions are used throughout this report.