



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2006-101***

***Norfolk Southern
Chattanooga, TN
December 16, 2006***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Norfolk Southern Corp. [NS]		1a. Alphabetic Code NS		1b. Railroad Accident/Incident No. 027451		
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident N/A		
3. Name of Railroad Responsible for Track Maintenance: Norfolk Southern Corp. [NS]		3a. Alphabetic Code NS		3b. Railroad Accident/Incident No. 027451		
4. U.S. DOT_AAR Grade Crossing Identification Number		5. Date of Accident/Incident Month Day Year 12 16 2006		6. Time of Accident/Incident 06:30: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM		
7. Type of Accident/Incident (single entry in code box)						
1. Derailment		4. Side collision		7. Hwy-rail crossing		
2. Head on collision		5. Raking collision		10. Explosion-detonation		
3. Rear end collision		6. Broken Train collision		11. Fire/violent rupture		
		9. Obstruction		12. Other impacts		
13. Other (describe in narrative) 01						
8. Cars Carrying HAZMAT 24		9. HAZMAT Cars Damaged/Derailed 4		10. Cars Releasing HAZMAT 0		
				11. People Evacuated 0		
				12. Division Central		
13. Nearest City/Town Chattanooga		14. Milepost (to nearest tenth) 0.7		15. State Abbr Code N/A TN		
				16. County HAMILTON		
17. Temperature (F) (specify if minus) 65 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 1		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		
				20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1		
21. Track Name/Number Main		22. FRA Track Code Class (1-9, X) 2		23. Annual Track Density (gross tons in millions) 34		
				24. Time Table Direction Code 1. North 3. East 1		
OPERATING TRAIN #1						
25. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car		A. Spec. MoW Equip. Code 1		
				26. Was Equipment Attended? 1. Yes 2. No 1		
				27. Train Number/Symbol 162AA1		
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 22 MPH R		30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits			30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
29. Trailing Tons (gross tonnage, excluding power units) 11114				e N/A N/A N/A N/A		
31. Principal Car/Unit		a. Initial and Number		b. Position in Train		
(1) First involved (derailed, struck, etc)		N/A		24		
(2) Causing (if mechanical cause reported)		0		0		
				c. Loaded (yes/no) no		
				32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.		
				Alcohol Drugs N/A N/A		
				33. Was this consist transporting passengers? (Y/N) N/A		
34. Locomotive Units		a. Head End		b. Mid Train		
		b. Manual		c. Remote		
		d. Manual		c. Remote		
(1) Total in Train		3		0		
(2) Total Derailed		0		0		
				35. Cars		
				a. Freight		
				b. Pass.		
				c. Freight		
				d. Pass.		
				e. Caboose		
				(1) Total in Equipment Consist		
				93		
				(2) Total Derailed		
				26		
36. Equipment Damage This Consist		37. Track, Signal, Way, & Structure Damage		38. Primary Cause Code		
74700		80000		H520		
				39. Contributing Cause Code N/A		
Number of Crew Members			Length of Time on Duty			
40. Engineer/Operators N/A		41. Firemen 0		42. Conductors 1		
				43. Brakemen 0		
				44. Engineer/Operator Hrs 10 Mi 20		
				45. Conductor Hrs 10 Mi 20		
Casualties to:		46. Railroad Employees		47. Train Passengers		
Fatal		0		0		
Nonfatal		N/A		0		
				48. Other		
				49. EOT Device? 1. Yes 2. No 1		
				50. Was EOT Device Properly Armed? 1. Yes 2. No 1		
				51. Caboose Occupied by Crew? 1. Yes 2. No N/A		
OPERATING TRAIN #2						
52. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car		A. Spec. MoW Equip. Code N/A		
				53. Was Equipment Attended? 1. Yes 2. No N/A		
				54. Train Number/Symbol N/A		
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated N/A MPH N/A		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

56. Trailing Tons (gross tonnage, excluding power units)		N/A		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s)		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		N/A							
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.				Alcohol		Drugs					
(1) First involved (derailed, struck, etc)		N/A		N/A		N/A						N/A		N/A					
(2) Causing (if mechanical cause reported)		N/A		N/A		N/A		60. Was this consist transporting passengers? (Y/N)				N/A							
61. Locomotive Units		a. Head End		Mid Train		Rear End		62. Cars		Loade		Empty		e. Caboose					
				b. Manual		c. Remote				a. Freight		b. Pass.		c. Freight		d. Pass.			
(1) Total in Train		N/A		N/A		N/A		N/A		(1) Total in Equipment Consist		N/A		N/A		N/A			
(2) Total Derailed		N/A		N/A		N/A		N/A		(2) Total Derailed		N/A		N/A		N/A			
63. Equipment Damage This Consist		N/A		64. Track, Signal, Way, & Structure Damage		N/A		65. Primary Cause Code		N/A		66. Contributing Cause Code		N/A					
Number of Crew Members				Length of Time on Duty															
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator		72. Conductor									
N/A		N/A		N/A		N/A		Hrs N/A Mi N/A		Hrs N/A Mi N/A									
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		77. Was EOT Device Properly Armed?									
Fatal		N/A		N/A		N/A		1. Yes 2. No N/A		1. Yes 2. No N/A									
Nonfatal		N/A		N/A		N/A		78. Caboose Occupied by Crew?		N/A									
								1. Yes 2. No											
Highway User Involved								Rail Equipment Involved											
79. Type		C. Truck-Trailer.		F. Bus		J. Other Motor Vehicle		Code		83. Equipment		3. Train (standing)		6. Light Loco(s) (moving)		Code			
A. Auto		D. Pick-Up Truck		G. School Bus		K. Pedestrian				1. Train(units pulling)		4. Car(s) (moving)		7. Light(s) (standing)					
B. Truck		E. Van		H. Motorcycle		M. Other (spec. in narrative)		N/A		2. Train(units pushing)		5. Car(s) (standing)		8. Other (specify in narrative)		N/A			
80. Vehicle Speed (est. MPH at impact)		N/A		81. Direction geographical		Code		84. Position of Car Unit in Train		N/A									
				1. North 2. South 3. East 4. West		N/A													
82. Position				Code		85. Circumstance		Code											
1. Stalled on Crossing		2. Stopped on Crossing		3. Moving Over Crossing		4. Trapped		N/A		1. Rail Equipment Struck Highway User									
										2. Rail Equipment Struck by Highway User									
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?				Code		86b. Was there a hazardous materials release by		Code											
1. Highway User		2. Rail Equipment		3. Both		4. Neither		N/A		1. Highway User		2. Rail Equipment		3. Both		4. Neither			
86c. State here the name and quantity of the hazardous materials released, if any.																			
N/A																			
87. Type of Crossing		1. Gates		4. Wig Wags		7. Crossbucks		10. Flagged by crew		88. Signaled Crossing Warning		Code		89. Whistle Ban		Code			
		2. Cantilever FLS		5. Hwy. traffic signals		8. Stop signs		11. Other (spec. in narr.)		(See instructions for codes)				1. Yes					
		3. Standard FLS		6. Audible		9. Watchman		12. None						2. No					
Code(s)		N/A		N/A		N/A		N/A						3. Unknown		N/A			
90. Location of Warning				Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code							
1. Both Sides						1. Yes				1. Yes									
2. Side of Vehicle Approach						2. No				2. No									
3. Opposite Side of Vehicle Approach				N/A		3. Unknown		N/A		3. Unknown									
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code							
N/A		1. Male				1. Yes				1. Drove around or thru the Gate		4. Stopped on Crossing							
		2. Female		N/A		2. No				2. Stopped and then Proceeded		5. Other (specify in narrative)							
						3. Unknown		N/A		3. Did not Stop									
97. Driver Passed Standing Highway Vehicle				Code		98. View of Track Obscured by (primary obstruction)		Code											
1. Yes		2. No		3. Unknown		1. Permanent Structure				3. Passing Train		5. Vegetation		7. Other (specify in narrative)					
						2. Standing Railroad Equipment		4. Topography		6. Highway Vehicle		8. Not obstructed							
101. Casualties to Highway-Rail Crossing Users				Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code					
				N/A		N/A		1. Killed		2. Injured		3. Uninjured		N/A		1. Yes		2. No	
								102. Highway Vehicle Property Damage (est. dollar damage)		N/A		103. Total Number of Highway-Rail Crossing Users (include driver)		N/A					
104. Locomotive Auxiliary Lights?				Code		105. Locomotive Auxiliary Lights Operational?		Code											
1. Yes		2. No		N/A		1. Yes		2. No											
106. Locomotive Headlight Illuminated?				Code		107. Locomotive Audible Warning Sounded?		Code											
1. Yes		2. No		N/A		1. Yes		2. No											


108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

HQ-2006-101
sketch.jpg

U.S. Department of Transportation Federal Railroad Administration
FRA FACTUAL RAILROAD ACCIDENT REPORT
FRA File # HQ-101-2006
108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

On December 16, 2006, at 6:30 a.m. Eastern Standard Time (EST), northbound Norfolk Southern (NS) Train 162AA15 (162) detailed 33 cars en route from Sheffield, Alabama (AL) to Chattanooga, Tennessee (TN). The accident occurred in Chattanooga on the No. 1 Main track of NS's Central Division at milepost (MP) 0.7 on the AGS North District. Norfolk Southern officials attributed this derailment to improper train handling and charged the engineer with violating NS's Train Handling Rule (NS-1) L-210. A review of the event recorder for the second locomotive (NS 9460 Dash 9) and the third locomotive (UP 4304 SP700a) revealed all three locomotives were being operated in power and dynamic braking. NS Train Handling Rule, L-210 (2.2) Dynamic Brake status in part: If a locomotive consist includes one or more units equipped with Standard dynamic brake, not more than the equivalent of 20-steps of dynamic braking may be used on the head end of a train. If all units in the consist are equipped with Extended Range dynamic braking, not more than the equivalent of 18-steps of dynamic braking may be used on the head end of a train. In NS Train Handling Rule L-207 a chart identifies the types of locomotives used on train 162AA15. The examples shown indicate that the type of locomotives on train 162AA15 have the equivalent adhesion, when operated together, of 26-steps of dynamic braking force.

HQ-101-2006
December 16, 2006
NS Train 162AA15
NS No. Main - North Direction
MP 0.7 AGS
Chattanooga, TN



109. SYNOPSIS OF THE ACCIDENT

On December 16, 2006, at 6:30 a.m. Central Standard Time (CST), northbound Norfolk Southern (NS) Train 162AA15 derailed 33 cars en route from Sheffield, Alabama (AL) to Chattanooga, Tennessee (TN). The accident occurred in Chattanooga on the NS Central Division at milepost (MP) 0.7 on the AGS North District (Chattanooga Terminal). The method of operation at this location is Automatic Block System (ABS) and Remote Control (RC). The maximum authorized speed for this location is 25 miles per hour (mph).

The train crew for Train 162AA15 consisted of an engineer and a conductor. Both crew members reported for duty in Sheffield at 7:10 p.m. on December 15, 2006. Sheffield is the home terminal for both crew members. The train consisted of three locomotives, NS 9016, NS 9460, UP 4304, 127 cars (93 loads and 34 empties). The train was 7,185 ft in length and weighed 11,685 tons.

The engineer was operating from lead Locomotive NS 9016. It was reported that the engineer advised NS officials that he was operating with the dynamic brakes fully applied as the train entered a 3-degree right-hand curve and was operating at a recorded speed of 23 mph when the derailment occurred. The engineer said he made a minimum reduction with the automatic brake and several minutes later the train came to a complete stop. An emergency brake application did not occur. The engineer said he had a good reading from the rear-end telemetry device, but when he released the brakes and tried to continue northward there was no movement. The conductor walked the train and discovered that the 24th through the 56th cars had derailed.

There was a total of 24 hazardous material cars in the train and four derailed. All cars derailed were standing upright with no hazardous material spillage and there were no injuries. The NS mechanical department reported \$74,700 in equipment damage and the engineering department reported \$80,000 in track damage.

At the time of the derailment, weather conditions were clear, dark, and 65°F.

The probable cause of the derailment is the use of dynamic brakes with excessive axles.

110. NARRATIVE

Circumstances Prior To The Accident

The crew for Train 162AA15 consisted of an engineer and conductor. On December 15, 2006, at 7:10 p.m., both crew members reported for duty in Sheffield. Sheffield is the home terminal for both crew members. Prior to reporting for duty each crew member received more than the statutory off-duty period. Their train consisted of three locomotives, NS 9016, NS 9460, UP 4304, 127 cars (93 loads and 34 empties). The train was 7,185 ft long and weighed 11,685 tons.

The locomotives for Train 162AA15 were located in the locomotive shop and the crew performed a locomotive inspection. The train's consist was located in two separate tracks in the departure yard. They made up their train, received a Class 1 brake test by the mechanical department, and departed Sheffield about 9:30 p.m. Prior to departing Sheffield, the train crew conducted a job briefing with the train dispatcher and reviewed their train bulletins. Their orders indicated they would encounter two slow orders en route.

Leaving Sheffield Yard the train operates on the NS Memphis East District from MP 402.8A to Stevenson, AL, MP 281.1A. The method of operation on the Memphis East District is Track Warrant Authority (TWA) and ABS. From Stevenson to Wauhatchie, TN, MP 248.1A, the NS operates under trackage rights over CSX Transportation (CSX) for a distance of 34 miles. The method of operation for trains operating on CSX between these two locations is Traffic Control Systems (TCS) and the maximum authorized speed on CSX is 60 mph. At Wauhatchie, NS trains will transfer back to the NS (MP 5.5) and operate on NS AGS North District (Chattanooga Terminal) to Chattanooga. The method of operation on the AGS North is TWA and ABS to MP 5.3 with a maximum speed of 50 mph. MP 5.3 to MP 0.0 is referred to as the Chattanooga Terminal and the method of operation is RC and ABS. The maximum authorized speed is 25 mph.

Train 162AA15 approached the derailment site traveling in a northward direction and received a clear signal at North Tunnel, MP 3.0. The engineer and conductor were located in the operating compartment of Locomotive NS 9016. The engineer was seated at the controls on the right side of the locomotive and the conductor was seated in the front seat on the left side of the locomotive. The train exited the North Tunnel on single main track at MP 2.2.

At MP 2.1, Train 162AA15 entered no. 1 main track traversing a 1.5-degree left-hand curve with a .09 descending grade. At MP 2.0, the track is tangent. At MP 1.9, the train entered a 1-degree right-hand curve, on a .06 ascending grade, and exiting the curve to MP 1.8 the track is the tangent. At MP 1.7, the train entered a 3-degree right-hand curve on a .51 ascending grade. The train exited the curve at MP 1.2 onto tangent track with a .22 ascending grade. At MP .07, the train entered a 3-degree right-hand curve with a .66 descending grade.

The timetable direction for this movement is south to north and the geographical direction is west to east. Timetable direction will be used throughout this accident.

The Accident

Train 162AA15 received a clear signal at North Tunnel, MP 3.0 AGS. The event recorder located on the lead locomotive indicated Train 162AA15 was traveling at 23 mph. Near MP.39, the train's speed began to increase and the engineer made a service application of the train air brakes. As the speed decreased, the engineer released the train air brakes, but left the train dynamic brakes applied. The train speed reached 5 mph, the engineer applied power (throttle position 3), and the amperage increased to 1,016 amps when the train stalled. After the engineer applied power and the train did not move, he concluded a problem existed somewhere in the train. The conductor dismounted the locomotive and walked back to inspect the train. He reported finding an air leak between the 10th and 11th cars. He reconnected the hoses and made sure the air hose gaskets were sealed. He continued his inspection and discovered the 24th through the 52nd cars were derailed, but remained upright. He notified the engineer who contacted the train dispatcher about the derailment.

Analysis and Conclusion

A review of the event recorder data from the lead locomotive (NS 9016) revealed the locomotives were placed in idle from power at MP 1.0 AGS with the train speed at 23 mph. The locomotives remained in idle to MP 0.56 AGS where the dynamic brake was applied with the speed of the train maintaining 23 mph through this entire section. The dynamic was allowed to build amperage gradually from MP 0.56 AGS to MP 0.39 AGS reaching maximum amperage on the lead unit of 712 amps and the speed of the train remaining at 23 mph.

NS officials attributed this derailment to improper train handling according to NS Train Handling Rule (NS-1) L-210. A review of the event recorders from the second locomotive (NS 9460) and the third locomotive (UP 4304) revealed all three locomotives were being operated in power and dynamic braking. The rear end of Train 162AA15 was cresting a 0.51 percent descending grade at MP 1.7 AGS (as the dynamic brakes reached the maximum amperage) and the first service automatic brake application was initiated.

The dynamic brakes for each of the locomotives operated on Train 162AA15 were all on line and providing retarding force to control train speed. The retarding force (adhesion) produced by these three locomotives (when operated in unison) exceeded the amount of adhesion allowed by NS. NS Train Handling Rule, L-210 [2.2] Dynamic Brake states in part, a locomotive consist includes one or more units equipped with standard dynamic brake, the equivalent of 20-axles of dynamic braking may be used on the head end of a train. If all units in the consist are equipped with extended range dynamic braking, not more than the equivalent of 18-axles of dynamic braking may be used on the head end of a train. NS Train Handling Rule L-207 identifies the types of locomotives used on Train 162AA15. The example shown indicates that the type of locomotives used for Train 162AA15 have the equivalent adhesion, when operated together, of 25-axles of dynamic braking force.

Fatigue Analysis:

FRA uses an overall effectiveness rate of 77.5 percent as the baseline for fatigue analysis, which is equivalent to a blood alcohol content (BAC) of 0.05. At or above this baseline, we do not consider fatigue as probable for any employee. Software sleep settings vary according to information obtained from each employee. If an employee does not provide sleep information, FRA uses the default software settings.

The information for two employees follows:

Engineer assigned to Train 162AA15;
Sleep setting Excellent at Home - Good Away
Overall Effectiveness = 52.40 %
Lapse Index = 10.0
Reaction Time = 191
Chronic Sleep Debt = 12.08
Hours of Continuous Wakefulness = 24.52
Time of Day (military) = 0630
BAC Equivalent = >0.08
Conclusion: Fatigue was probable for this employee.

Conductor assigned to Train 162SS15
Sleep setting Excellent at Home - Good Away
Overall Effectiveness = 48.47
Lapse Index = 10.0
Reaction Time = 206
Chronic Sleep Debt = 13.43
Hours of Continuous Wakefulness = 24.52
Time of Day (military) = 0630
BAC Equivalent = >0.08
Conclusion: Fatigue was probable for this employee.

FRA obtained fatigue related information, including a 10-day work history, for the engineer and conductor operating Train 162AA15. FRA concluded fatigue was a probable cause for the engineer and conductor of Train 162AA15.

The probable cause of the derailment is the use of dynamic brakes with excessive axles.