



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2006-102***

***Union Pacific
Peck, KS
December 22, 2006***


Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP]			1a. Alphabetic Code UP			1b. Railroad Accident/Incident No. 1206WH013								
2. Name of Railroad Operating Train #2 Union Pacific RR Co. [UP]			2a. Alphabetic Code UP			2b. Railroad Accident/Incident 1206WH013								
3. Name of Railroad Responsible for Track Maintenance: Union Pacific RR Co. [UP]			3a. Alphabetic Code UP			3b. Railroad Accident/Incident No. 1206WH013								
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month Day Year 12 22 2006			6. Time of Accident/Incident 02:00: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM								
7. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision			4. Side collision 5. Raking collision 6. Broken Train collision								
			7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction			10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts								
						13. Other (describe in narrative) 05								
8. Cars Carrying HAZMAT 7		9. HAZMAT Cars Damaged/Derailed 0		10. Cars Releasing HAZMAT 0		11. People Evacuated 0		12. Division Wichita						
13. Nearest City/Town Riverdale			14. Milepost (to nearest tenth) 267.5		15. State Abbr Code N/A KS		16. County SUMNER							
17. Temperature (F) (specify if minus) 40 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 2		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1								
21. Track Name/Number Single Main			22. FRA Track Code Class (1-9, X) 4		23. Annual Track Density (gross tons in millions) 12		24. Time Table Direction Code 1. North 3. East 2							
OPERATING TRAIN #1														
25. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars								
			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car			A. Spec. MoW Equip. Code 1		26. Was Equipment Attended? 1. Yes 2. No 1						
								27. Train Number/Symbol RWTKC-21						
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH R			30. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking			g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits								
29. Trailing Tons (gross tonnage, excluding power units) 1393						m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) n N/A N/A N/A N/A								
						30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0								
31. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded (yes/no)	32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.									
(1) First involved (derailed, struck, etc)		N/A	1	no	Alcohol		Drugs							
(2) Causing (if mechanical cause reported)		0	0	N/A	0		0							
						33. Was this consist transporting passengers? (Y/N) N								
34. Locomotive Units		a. Head End	b. Mid Train		c. Rear End	35. Cars		Loaded						
			b. Manual	c. Remote	d. Manual	e. Remote		Empty						
(1) Total in Train		2	0	0	0	0	(1) Total in Equipment Consist	0						
(2) Total Derailed		0	0	0	0	0	(2) Total Derailed	0						
								a. Freight						
								b. Pass.						
								c. Freight						
								d. Pass.						
								e. Caboose						
36. Equipment Damage This Consist 70000			37. Track, Signal, Way, & Structure Damage 0			38. Primary Cause Code H401			39. Contributing Cause Code H525					
Number of Crew Members						Length of Time on Duty								
40. Engineer/Operators N/A		41. Firemen 0		42. Conductors 1		43. Brakemen 0		44. Engineer/Operator Hrs 3 Mi 00			45. Conductor Hrs 3 Mi 00			
Casualties to:		46. Railroad Employees		47. Train Passengers		48. Other		49. EOT Device? 1. Yes 2. No 1			50. Was EOT Device Properly Armed? 1. Yes 2. No 1			
Fatal		0		0		0		51. Caboose Occupied by Crew? 1. Yes 2. No			N/A			
Nonfatal		N/A		0		0								
OPERATING TRAIN #2														
52. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car					
									A. Spec. MoW Equip. Code 1		53. Was Equipment Attended? 1. Yes 2. No 1			
											54. Train Number/Symbol LV05421			
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 25 MPH E			57. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control			g. Automatic block h. Current of traffic			m. Special instructions n. Other than main track			57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable		

56. Trailing Tons (gross tonnage, excluding power units)		2467		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s)		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		0											
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.				Alcohol		Drugs									
(1) First involved (derailed, struck, etc)		UP1674		1		N/A						0		0									
(2) Causing (if mechanical cause reported)		0		0		N/A		60. Was this consist transporting passengers? (Y/N)				N/A											
61. Locomotive Units		a. Head End		Mid Train		Rear End		62. Cars		Loaded		Empty		e. Caboose									
				b. Manual		c. Remote				a. Freight		b. Pass.		c. Freight		d. Pass.							
(1) Total in Train		2		0		0		0		0		(1) Total in Equipment Consist		6		0		56		0		0	
(2) Total Derailed		2		0		0		0		0		(2) Total Derailed		0		0		1		0		0	
63. Equipment Damage This Consist		310125		64. Track, Signal, Way, & Structure Damage		21810		65. Primary Cause Code		H401		66. Contributing Cause Code		H525									
Number of Crew Members				Length of Time on Duty																			
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator		72. Conductor													
1		0		1		0		Hrs 11 Mi 00		Hrs 11 Mi 00													
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		77. Was EOT Device Properly Armed?													
Fatal		0		2		0		1. Yes 2. No 1		1. Yes 2. No 1													
Nonfatal		0		0		0		78. Caboose Occupied by Crew?		N/A													
								1. Yes 2. No															
Highway User Involved						Rail Equipment Involved																	
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle		Code		83. Equipment		3. Train (standing)		6. Light Loco(s) (moving)		Code											
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian				N/A		1. Train(units pulling)		4. Car(s)(moving)		7. Light(s) (standing)		N/A											
B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)				N/A		2. Train(units pushing)		5. Car(s)(standing)		8. Other (specify in narrative)		N/A											
80. Vehicle Speed (est. MPH at impact)		N/A		81. Direction geographical		Code		84. Position of Car Unit in Train		N/A													
				1. North 2. South 3. East 4. West		N/A																	
82. Position				Code		85. Circumstance		Code															
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				N/A		1. Rail Equipment Struck Highway User		N/A															
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?				Code		86b. Was there a hazardous materials release by		Code															
1. Highway User 2. Rail Equipment 3. Both 4. Neither				N/A		1. Highway User 2. Rail Equipment 3. Both 4. Neither		N/A															
86c. State here the name and quantity of the hazardous materials released, if any.																							
N/A																							
87. Type of Crossing		1. Gates		4. Wig Wags		7. Crossbucks		10. Flagged by crew		88. Signaled Crossing Warning		Code		89. Whistle Ban		Code							
		2. Cantilever FLS		5. Hwy. traffic signals		8. Stop signs		11. Other (spec. in narr.)		(See instructions for codes)				1. Yes									
		3. Standard FLS		6. Audible		9. Watchman		12. None				N/A		2. No									
Code(s)		N/A		N/A		N/A		N/A				N/A		3. Unknown		N/A							
90. Location of Warning				Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code											
1. Both Sides						1. Yes				1. Yes													
2. Side of Vehicle Approach						2. No				2. No													
3. Opposite Side of Vehicle Approach				N/A		3. Unknown		N/A		3. Unknown		N/A											
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code											
N/A		1. Male		N/A		1. Yes 2. No 3. Unknown		N/A		1. Drove around or thru the Gate		4. Stopped on Crossing											
		2. Female								2. Stopped and then Proceeded		5. Other (specify in narrative)		N/A									
										3. Did not Stop				N/A									
97. Driver Passed Standing Highway Vehicle		Code		98. View of Track Obscured by (primary obstruction)		Code																	
1. Yes 2. No 3. Unknown		N/A		1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative)		N/A				2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed		N/A											
101. Casualties to Highway-Rail Crossing Users		Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code											
		N/A		N/A		1. Killed 2. Injured 3. Uninjured		N/A		1. Yes 2. No		N/A											
						102. Highway Vehicle Property Damage (est. dollar damage)		N/A		103. Total Number of Highway-Rail Crossing Users (include driver)		N/A											
104. Locomotive Auxiliary Lights?				Code		105. Locomotive Auxiliary Lights Operational?		Code															
1. Yes 2. No				N/A		1. Yes 2. No		N/A															
106. Locomotive Headlight Illuminated?				Code		107. Locomotive Audible Warning Sounded?		Code															
1. Yes 2. No				N/A		1. Yes 2. No		N/A															

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

HQ-
2006102_S
ketch.jpg



109. SYNOPSIS OF THE ACCIDENT

At 2 a.m. (c.s.t.), on December 22, 2006, Union Pacific Railroad Company (UP) northbound local freight Train Symbol LV054-21 collided with empty UP rock Train Symbol RWTCK-21. The collision occurred at milepost 267.5 on the Enid Subdivision of the Wichita Service Unit, at Riverdale, Kansas, 23 miles south of Wichita, Kansas.

Two locomotives and one car on the northbound freight train derailed with no hazardous material release, resulting in \$401,935 damage to track and equipment. All four crew members were taken for treatment of minor injuries and for Federal Railroad Administration (FRA) Post-Accident Toxicological Testing.

The weather was dark and cloudy and the temperature was 40 degrees Fahrenheit.

The probable cause of the accident was failure of southbound Train Symbol RWTCK-21 to stop in the clear of the main track.

110. NARRATIVE

The following information was obtained from an investigation that was conducted by the Federal Railroad Administration.

Circumstances Prior to the Accident

Train Symbol RWTCK-21 (Train No.1)

On December 21, 2006, at 11 p.m. (c.s.t.), the crew of Train Symbol RWTCK-21 went on duty at their away-from-home terminal of Wichita. The crew consisted of a conductor and an engineer, both of whom had received the required statutory off-duty rest period prior to reporting for duty. They departed Wichita at approximately 11:30 p.m., in a crew van after receiving the required track warrants, track bulletins, and other documents needed for their trip. Their train was at Midland siding approximately 8 miles south of Wichita. They arrived at Midland at 12 midnight on December 22, 2006. After coupling their train, a Class 1 air brake test was performed prior to departing Midland. The train consisted of two locomotives, UP 2033 and UP 2068; 48 empty rock cars; 1,393 trailing tons; and was 2,057 feet in length.

As the southbound train approached the accident area, the locomotive engineer was seated on the west side and the conductor was seated on the east side of the locomotive. The engineer was operating the train and the conductor was reviewing track warrants in anticipation of receiving a mandatory directive from the train dispatcher. The track is tangent both north and south from the accident site for several miles.

The railroad timetable and geographic direction was south.

Train Symbol LV054-21 (Train No.2)

On December 21, 2006, at 3:30 p.m. (c.s.t.), the crew of Train Symbol LV054-21 went on duty at their home terminal of Chickasha, Oklahoma. The crew consisted of a conductor and an engineer, both of whom had received the required statutory off-duty rest period prior to reporting for duty. They departed Chickasha at approximately 6 p.m., after receiving the required track warrants, track bulletins, and other documents needed for their trip. No inspections or air brake tests were required prior to their departure, and none were performed. A Class 1 air brake test was performed on the train at Chickasha by a yard switching crew, prior to the crew reporting for duty. The train consisted of two locomotives, UP 1674 and SSW 9653; 6 loaded cars; 56 empties; 2,467 trailing tons; and was 3,868 feet in length.

As the north bound train approached the accident area, the locomotive engineer was seated on the east side and the conductor was seated on the west side of the locomotive. The engineer was operating the train and the conductor was reviewing track warrants in anticipation of receiving a mandatory directive from the train dispatcher.

Approaching the accident the track is tangent both north and south. The grade at the north switch is level, ascending to a 0.54-percent descending grade at the mid-point of the siding or approximately 2,750 feet from the south siding switch. From the mid-point of the siding there is a 0.65-percent descending grade to the south switch.

The Accident

Train Symbol RWTCK-21

At approximately 1:55 a.m., after lining the north siding switch, Train Symbol RWTCK-21 proceeded south on the Riverdale siding. The Riverdale siding is approximately 5,500 feet in length. While traveling south, the speed varied from 10 to 13 mph. Approaching the south switch, the engineer used the locomotive brakes (independent brakes) to control the train. Meanwhile, the conductor, seated on the opposite side of the cab from the engineer, was reviewing paperwork. No obstructions were evident in either direction.

The engineer of Train Symbol RWTCK-21 dimmed his headlight so as not to "blind" the opposing train. After dimming the headlight, he could not see the clearance point very well. He applied the independent brake and realized the train would not stop before fouling the main track. The engineer initiated an emergency application of the train and engine brakes. Nearing the south end of the siding, the conductor stated he asked the engineer if they were able to stop before reaching the switch. The engineer was talking on the radio and did not respond immediately. The conductor then asked the engineer if the train was in emergency. The engineer responded that it was.

The train came to rest approximately 30 feet from the switch, fouling the main track. At this time the crew of Train Symbol RWTCK-21 could see the northbound train approaching. The engineer made a third attempt to contact the northbound train and warn them to stop. The engineer of the northbound train replied that he had placed his train in emergency. A few seconds later, the conductor went to the other side of the locomotive cab and stood behind the engineer's seat.

Impact followed, and the northbound train came to rest approximately four car-lengths north of the lead locomotive of Train Symbol RWTCK-21.

Train Symbol LV054-21

Approaching the accident site, the crew was talking to the UP Enid Subdivision dispatcher and the crew haul driver on the radio. The crew was coordinating a convenient location to secure the train so the crew haul driver could transport them from Midland siding to their final release point, Wichita, KS. Due to these conversations over the radio, the crew was not able to hear the warning of southbound Train Symbol RWTCK-21, until it was too late to stop.

The train approached Riverdale at approximately 40 mph. The maximum authorized speed at this location is 40 mph. Their track warrant was in effect to the North siding switch at Riverdale. The crew had 1 hour 30 minutes left to work at the time of the accident. The crew was planning to secure the train at Midland siding, approximately 10 miles north of Riverdale. It is estimated that impact occurred at 20 mph. The maximum authorized speed for this particular type of train is 40 mph. The event recorders on Train Symbol LV054-21 could not be downloaded by local UP management. The event recorders on Train Symbol LV054-21 were sent to UP headquarters for data retrieval.

Analysis and Conclusions

Analysis

FRA post-accident toxicological testing was performed on the crew members of both trains. The results were negative on all employees.

Conclusions

The crew of Train Symbol RWTCK-21 failed to stop their train before fouling the main track. In addition, the crew of Train Symbol RWTCK-21 contributed to the accident by improper use of the independent (locomotive) brakes.

The engineer did not follow UP Air Brake and Train Handling Rule 33.6.4 (B), Stopping, Level or Descending Grade without Dynamic Brakes, Slack Bunched.:

1. If in power, gradually reduce the throttle to IDLE.
2. Wait for the slack to adjust.
3. At a sufficient distance from the stop, make a minimum brake pipe reduction and actuate.
4. Make further split reduction(s) as needed and actuate. Allow locomotive to develop draft forces.
5. As the train comes to a stop, make a final brake pipe reduction and allow the locomotive brakes to apply.

Probable Cause

The Federal Railroad Administration determined that the contributing cause is H525: Independent (Engine) brake, improper use (Except Actuation).

The Federal Railroad Administration found that the primary cause of the accident was H401: Failure to stop train in the clear.