



***Federal Railroad Administration  
Office of Safety  
Headquarters Assigned  
Accident Investigation Report  
HQ-2005-09***

***Norfolk Southern (NS)  
Tarentum, Pennsylvania  
January 31, 2005***

***Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.***

1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP ]		1a. Alphabetic Code UP		1b. Railroad Accident/Incident No. 0106LV019	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident N/A	
3. Name of Railroad Responsible for Track Maintenance: Union Pacific RR Co. [UP ]		3a. Alphabetic Code UP		3b. Railroad Accident/Incident No. N/A	
4. U.S. DOT_AAR Grade Crossing Identification Number		5. Date of Accident/Incident Month Day Year 01 31 2006		6. Time of Accident/Incident 11:45: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM	
7. Type of Accident/Incident (single entry in code box)					
1. Derailment		4. Side collision		7. Hwy-rail crossing	
2. Head on collision		5. Raking collision		10. Explosion-detonation	
3. Rear end collision		6. Broken Train collision		11. Fire/violent rupture	
		9. Obstruction		12. Other impacts	
13. Other (describe in narrative)   01					
8. Cars Carrying HAZMAT 42		9. HAZMAT Cars Damaged/Derailed 28		10. Cars Releasing HAZMAT 0	
				11. People Evacuated 0	
				12. Division Livonia/Lufkin	
13. Nearest City/Town Timpson		14. Milepost (to nearest tenth) 162.90		15. State Abbr Code N/A TX	
16. County SHELBY					
17. Temperature (F) (specify if minus) 69 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark   2		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow   1	
20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry   1					
21. Track Name/Number Single Main Track		22. FRA Track Code Class (1-9, X) 4		23. Annual Track Density (gross tons in millions) 16.40	
24. Time Table Direction Code 1. North 3. East   2					

**OPERATING TRAIN #1**

25. Type of Equipment Consist (single entry)		1. Freight train		4. Work train		7. Yard/switching		A. Spec. MoW Equip. Code		26. Was Equipment Attended?		27. Train Number/Symbol	
2. Passenger train		5. Single car		8. Light loco(s).		9. Maint./inspect.car		1		1. Yes 2. No   1		MMEE WX 29	
3. Commuter train		6. Cut of cars		9. Maint./inspect.car									
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 28 MPH   R		30. Method(s) of Operation (enter code(s) that apply)		30a. Remotely Controlled Locomotive?									
29. Trailing Tons (gross tonnage, excluding power units) 5700		a. ATCS		g. Automatic block		m. Special instructions		0 = Not a remotely controlled		1 = Remote control portable		2 = Remote control tower	
		b. Auto train control		h. Current of traffic		n. Other than main track		3 = Remote control transmitter - more than one		remote control transmitter		0	
		c. Auto train stop		i. Time table/train orders		o. Positive train control							
		d. Cab		j. Track warrant control		p. Other (Specify in narrative) Code(s)							
		e. Traffic		k. Direct traffic control									
		f. Interlocking		l. Yard limits									

31. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded (yes/no)		32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.		Alcohol		Drugs	
(1) First involved (derailed, struck, etc)		N/A		35		yes				N/A		N/A	
(2) Causing (if mechanical cause reported)		NYC608728		35		yes		33. Was this consist transporting passengers? (Y/N)				N	

34. Locomotive Units		a. Head End		Mid Train		Rear End		35. Cars		a. Freight		b. Pass.		c. Freight		d. Pass.		e. Caboose	
(1) Total in Train		2		0		0		0		31		0		66		0		0	
(2) Total Derailed		0		0		0		0		2		0		35		0		0	

36. Equipment Damage This Consist		128123		37. Track, Signal, Way, & Structure Damage		830800		38. Primary Cause Code		E40C		39. Contributing Cause Code		N/A	
-----------------------------------	--	--------	--	--	--	--------	--	------------------------	--	------	--	-----------------------------	--	-----	--

**OPERATING TRAIN #2**


40. Engineer/Operators		41. Firemen		42. Conductors		43. Brakemen		44. Engineer/Operator		45. Conductor	
N/A		N/A		1		0		Hrs 8 Mi 05		Hrs 8 Mi 05	
Casualties to:		46. Railroad Employees		47. Train Passengers		48. Other		49. EOT Device?		50. Was EOT Device Properly Armed?	
Fatal		0		0		0		1. Yes 2. No   1		1. Yes 2. No   1	
Nonfatal		N/A		0		0		51. Caboose Occupied by Crew?			
								1. Yes 2. No		N/A	

**OPERATING TRAIN #2**

52. Type of Equipment Consist (single entry)		1. Freight train		4. Work train		7. Yard/switching		A. Spec. MoW Equip. Code		53. Was Equipment Attended?		54. Train Number/Symbol	
2. Passenger train		5. Single car		8. Light loco(s).		9. Maint./inspect.car		N/A		1. Yes 2. No   N/A		N/A	
3. Commuter train		6. Cut of cars		9. Maint./inspect.car									
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH   N/A		57. Method(s) of Operation (enter code(s) that apply)		57a. Remotely Controlled Locomotive?									
		a. ATCS		g. Automatic block		m. Special instructions		0 = Not a remotely controlled		1 = Remote control portable			
		b. Auto train control		h. Current of traffic		n. Other than main track							

56. Trailing Tons (gross tonnage, excluding power units)		N/A		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s)		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		N/A			
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.		Alcohol		Drugs			
(1) First involved (derailed, struck, etc)		0		N/A		N/A				N/A		N/A			
(2) Causing (if mechanical cause reported)		0		N/A		N/A		60. Was this consist transporting passengers? (Y/N)				N/A			
61. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote		62. Cars		Loade a. Freight b. Pass. c. Freight d. Pass.		Empty e. Caboose			
(1) Total in Train		0		0 0		0 0		(1) Total in Equipment Consist		0 0		0 0			
(2) Total Derailed		0		0 0		0 0		(2) Total Derailed		0 0		0 0			
63. Equipment Damage This Consist		0		64. Track, Signal, Way, & Structure Damage		0		65. Primary Cause Code		N/A		66. Contributing Cause Code		N/A	
Number of Crew Members						Length of Time on Duty									
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator		72. Conductor					
N/A		N/A		N/A		N/A		Hrs 0 Mi 0		Hrs 0 Mi 0					
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		77. Was EOT Device Properly Armed?					
Fatal		0		0		0		1. Yes 2. No N/A		1. Yes 2. No N/A					
Nonfatal		0		0		0		78. Caboose Occupied by Crew?						N/A	
								1. Yes 2. No							
Highway User Involved						Rail Equipment Involved									
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle		Code		83. Equipment		3. Train (standing) 6. Light Loco(s) (moving)		Code					
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian				N/A		1. Train(units pulling) 4. Car(s)(moving)		7. Light(s) (standing)		N/A					
B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)				N/A		2. Train(units pushing) 5. Car(s)(standing)		8. Other (specify in narrative)		N/A					
80. Vehicle Speed (est. MPH at impact)		N/A		81. Direction geographical		Code		84. Position of Car Unit in Train		N/A					
				1. North 2. South 3. East 4. West		N/A									
82. Position				Code		85. Circumstance		Code							
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				N/A		1. Rail Equipment Struck Highway User		N/A							
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?				Code		86b. Was there a hazardous materials release by		Code							
1. Highway User 2. Rail Equipment 3. Both 4. Neither				N/A		1. Highway User 2. Rail Equipment 3. Both 4. Neither		N/A							
86c. State here the name and quantity of the hazardous materials released, if any.															
N/A															
87. Type of Crossing		1. Gates 4. Wig Wags 7. Crossbucks 10. Flagged by crew		Code		88. Signaled Crossing Warning		Code		89. Whistle Ban		Code			
2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other (spec. in narr.)						(See instructions for codes)				1. Yes 2. No 3. Unknown					
3. Standard FLS 6. Audible 9. Watchman 12. None															
Code(s)		N/A N/A N/A		N/A N/A N/A N/A											
90. Location of Warning		Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code					
1. Both Sides				1. Yes 2. No 3. Unknown		N/A		1. Yes 2. No 3. Unknown		N/A					
2. Side of Vehicle Approach															
3. Opposite Side of Vehicle Approach		N/A													
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code			
0		1. Male 2. Female		N/A		1. Yes 2. No 3. Unknown		N/A		1. Drove around or thru the Gate 4. Stopped on Crossing 2. Stopped and then Proceeded 5. Other (specify in narrative) 3. Did not Stop		N/A			
97. Driver Passed Standing Highway Vehicle		Code		98. View of Track Obscured by (primary obstruction)		Code									
1. Yes 2. No 3. Unknown		N/A		1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative)		N/A									
101. Casualties to Highway-Rail Crossing Users		Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code			
		0		0		1. Killed 2. Injured 3. Uninjured		N/A		1. Yes 2. No		N/A			
104. Locomotive Auxiliary Lights?		Code		105. Locomotive Auxiliary Lights Operational?		Code									
1. Yes 2. No		N/A		1. Yes 2. No		N/A									
106. Locomotive Headlight Illuminated?		Code		107. Locomotive Audible Warning Sounded?		Code									
1. Yes 2. No		N/A		1. Yes 2. No		N/A									

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.  
HQ-09-  
2006.jpg



#### 109. SYNOPSIS OF THE ACCIDENT

A Southbound Union Pacific Freight Train traveling at a recorded speed of 28 mph, derailed 37 cars, all remaining upright, on January 31, 2006, at 11:45 am. The accident occurred 2.1 miles South of Timpson, TX at UP milepost 162.9 on the UP's Southern Region, Livonia Service Unit, Lufkin Subdivision. The train had been operating on a 25 mph speed restriction for the previous 4 miles. The reason for the speed restriction was defective tie conditions.

Twenty eight of the derailed cars were Residue HAZMAT cars. There was no HAZMAT release and no evacuations. Amtrak does not operate on this subdivision. There were no casualties.

Total Estimated damage \$958,923.00 (equipment \$128,123.00 ; track \$830,800.00)

At the time of the accident it was daylight and clear with calm winds. The temperature was 69 degrees F.

The cause of the accident was Side Bearing Clearance Insufficient on loaded car NYC 608728.

#### 110. NARRATIVE

##### Circumstances Prior to the Accident:

The crew of train MMEEWX-29 included a locomotive engineer and a conductor. They first went on duty at 3:40 a. m. CST, January 31, 2006 at River Front Yard in Shreveport, LA. This is an away from home terminal for both crew members. Both crew members had received more than the statutory off duty period, prior to reporting for duty.

Their assigned freight train consisted of two locomotives, 31 loaded and 66 empty cars of several varieties. The train was 6024 feet long and weighed 5700 tons. The train was scheduled to travel to Englewood Yard, Houston, TX with no pick ups or set outs en route. The train was a detour train originating on the CSXT railroad at Waycross, GA and interchanged to the Union Pacific Railroad at Memphis, TN. The train originated as Q60125 on January 25, 2006 and received a Class I Brake Test and inspection at Waycross, Ga.

As the Southbound train approached the accident area, the locomotive engineer was seated at the controls on the West side of the leading locomotive. The conductor was seated on the East side of the leading locomotive.

##### Topography:

In this area of the railroad there is over 4000 feet of tangent track leading into a right hand 2 degree 6 minute curvature with a descending grade of .67% at the point of derailment.

The railroad timetable direction of the train was South. The geographic direction of the train was South. Timetable directions are used throughout this report.

##### Method of Operation:

As indicated by timetable, the method of operation from the yard limits at the 225.8 MP to the 158.4 MP at Garrison is Track Warrant Authority.

##### Weather:

The weather was reported as clear, in daylight, with calm winds. The temperature was 69 degrees F.

##### The Accident:

The train was being operated at 28 mph approaching the accident area. This speed was recorded by the event recorder of the controlling locomotive. Maximum authorized timetable speed for this portion of track is 49 MPH; However, Track Bulletin Form A Number 093773 on Lufkin (612) to UP 4602 South At Shreveport. Do not exceed speed given. Line 8, from 167.5 MP to 161.5 MP, 25 MPH on Main Track. This slow order has been in effect since 01/04/06 1616 hours.

The engineer stated that he was operating the locomotives in dynamic braking and as the train was descending the .67% grade the train started dragging down. The engineer had notched off on the throttle to zero and the train continued to slow down and went into emergency a few feet before it stopped.

Once the train stopped the conductor got off of the locomotives and started walking the train. After walking about 35 car lengths he discovered the derailed cars. Upon this discovery he notified the dispatcher that they had a derailment. It was discovered that a total of 37 cars were derailed and that 2 were loaded and the other

35 were empty. It was also discovered that 28 of the derailed cars were Residue HAZMAT cars. There was no HAZMAT release and no evacuations. Also there were no human casualties. Once the cars were re-railed they were moved to Appleby, TX for repairs.

Analysis:

The Manager of Train Operations at Lufkin, TX made the decision not to have the train crew drug tested.

During the accident investigation it was determined that the cause of the of the derailment was Stiff Trucks on NYC 608728, Loaded Gondola.

On 02/17/2006 FRA Inspectors From Marshall, TX and Houston, TX met with Foreman General from Alexandria, LA, Union Pacific Railroad to inspect NYC 608728 that was to be jacked and repaired.

Upon Inspection it was found that the subject car was equipped with Stucki Constant Contact Side Bearings. It was also discovered that on the "A" end of the car the right and left side, constant contact side bearings were in contact with the body bolster in a manner other than by design.

Measurements of the above subject side bearings were taken using the recommended method, as described by the equipment manufacturer of the constant contact side bearing. (A.Stucki Company, Yard and shop inspection pocket guide, Rev. 4/09/04, Section 3.1.3, page 39.)

The first inspection was made by measuring the vertical distance between the mounting surface of the constant contact side bearing and the body side bearing wear plate. Both bearings measured less than the 4 7/8 inch allowed.

The second inspection used the "Sum of Pairs Method" which requires the use of inside calipers and a steel rule. When using the sum of pairs method, I measured the right and left side of the truck constant contact side bearing. The vertical distance between the body side bearing wear plate and the truck bolster surface to which the side bearing cage is mounted, when measured using the sum of pairs method, the constant side bearings measured 9 3/8 inches.

Design measurements for constant contact side bearings of this type when using the sum of pairs method may be as low as 9 7/8 inch, or as high as 10 1/2 inch. No individual space should be less than 4 7/8 inch for any standard or extended travel side bearing.

Next the car was raised off the trucks on the "A" end. It was noted that the Center Plate was not setting all the way down into the bowl, as seen that there was no wear on the truck bolster bowl. Also it was noted that the constant contact side bearing blocks were crushed and broken at the "A-L" position. We then removed the Cap, Blocks and Rollers on both sides and lowered the car back down into the bowl and re-measured the constant contact side bearing clearance. The "A-R" measurements remained the same but the "A-L" measurements decreased by 1/8 inch.

The car was again raised and the side bearings re-assembled and a 1/4 inch shim placed into the bolster center plate bowl and the car lowered back into place. The constant contact side bearings were once again measured. On this measurement the sum of pairs method was used and the total measurement was 9 13/16 inches with no measurement less than 4 7/8 inch.

Conclusions:

It was determined from the measurements of the constant contact side bearings, the evidence of the condition of the side bearing blocks and the lack of wear on the center plate bowl, that the weight of the car had been riding completely on the constant contact side bearings and not allowing the "A" end truck to rotate properly. This allowed the "A" end truck to produce sufficient force onto the outside rail into the 2 degree 6 minute right hand curvature to turn the rail over and cause the derailment.