



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2005-31***

***BNSF Railway (BNSF)
Pueblo, Colorado
April 9, 2005***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 BURLINGTON NORTHERN SANTA FE CORPORATION		1a. Alphabetic Code BNSF		1b. Railroad Accident/Incident No. PR0405107	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident N/A	
3. Name of Railroad Responsible for Track Maintenance: BNSF Rwy Co. [BNSF]		3a. Alphabetic Code BNSF		3b. Railroad Accident/Incident No. PR0405107	
4. U.S. DOT_AAR Grade Crossing Identification Number		5. Date of Accident/Incident Month: 04 Day: 09 Year: 2005		6. Time of Accident/Incident 11:50: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM	
7. Type of Accident/Incident (single entry in code box) 1. Derailment 4. Side collision 7. Hwy-rail crossing 10. Explosion-detonation 13. Other (describe in narrative) 2. Head on collision 5. Raking collision 8. RR grade crossing 11. Fire/violent rupture 3. Rear end collision 6. Broken Train collision 9. Obstruction 12. Other impacts 01					
8. Cars Carrying HAZMAT 8	9. HAZMAT Cars Damaged/Derailed 4	10. Cars Releasing HAZMAT 0	11. People Evacuated 0	12. Division Powder River	
13. Nearest City/Town Pueblo		14. Milepost (to nearest tenth) 122.0	15. State Abbr Code N/A CO	16. County PUEBLO	
17. Temperature (F) (specify if minus) 53 F	18. Visibility (single entry) 1. Dawn 3. Dusk 2. Day 4. Dark Code: 4	19. Weather (single entry) 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow Code: 2	20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1		
21. Track Name/Number Single Main		22. FRA Track Code Class (1-9, X) 2	23. Annual Track Density (gross tons in millions) 38.24	24. Time Table Direction Code 1. North 3. East 1	
OPERATING TRAIN #1					
25. Type of Equipment Consist (single entry) 1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car		A. Spec. MoW Equip. Code 1		26. Was Equipment Attended? 1. Yes 2. No 1	
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 12 MPH R		30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits j N/A N/A N/A N/A			30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0
29. Trailing Tons (gross tonnage, excluding power units) 6286		31. Principal Car/Unit a. Initial and Number b. Position in Train c. Loaded (yes/no) (1) First involved (derailed, struck, etc) N/A 3 N/A (2) Causing (if mechanical cause reported) CSXT4786 3 N/A			
34. Locomotive Units a. Head End b. Mid Train c. Remote d. Manual e. Rear End (1) Total in Train 4 0 0 0 0 (2) Total Derailed 2 0 0 0 0		35. Cars (1) Total in Equipment Consist 49 (2) Total Derailed 25		36. Equipment Damage This Consist 207063 37. Track, Signal, Way, & Structure Damage 321375 38. Primary Cause Code E63L 39. Contributing Cause Code N/A	
40. Engineer/Operators N/A		41. Firemen 0		42. Conductors 1	
43. Brakemen 1		44. Engineer/Operator Hrs 7 Mi 20		45. Conductor Hrs 7 Mi 20	
Casualties to: Fatal 0 Nonfatal N/A		46. Railroad Employees 0		47. Train Passengers 0	
48. Other 0		49. EOT Device? 1. Yes 2. No 1		50. Was EOT Device Properly Armed? 1. Yes 2. No 1	
51. Caboose Occupied by Crew? 1. Yes 2. No 2					
OPERATING TRAIN #2					
52. Type of Equipment Consist (single entry) 1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car		A. Spec. MoW Equip. Code N/A		53. Was Equipment Attended? 1. Yes 2. No N/A	
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable

56. Trailing Tons (gross tonnage, excluding power units) 0		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A			
58. Principal Car/Unit (1) First involved (derailed, struck, etc) 0		a. Initial and Number 0		b. Position in Train 0		c. Loaded(yes/no) N/A		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol N/A Drugs N/A			
(2) Causing (if mechanical cause reported) 0		0		N/A		60. Was this consist transporting passengers? (Y/N) N/A					
61. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote		62. Cars		Loade a. Freight b. Pass. c. Freight d. Pass. e. Caboose	
(1) Total in Train 0		0		0		0		(1) Total in Equipment Consist 0		0	
(2) Total Derailed 0		0		0		0		(2) Total Derailed 0		0	
63. Equipment Damage This Consist 0		64. Track, Signal, Way, & Structure Damage 0		65. Primary Cause Code N/A		66. Contributing Cause Code N/A					
Number of Crew Members				Length of Time on Duty							
67. Engineer/Operators 0		68. Firemen 0		69. Conductors 0		70. Brakemen 0		71. Engineer/Operator Hrs 0 Mi 0		72. Conductor Hrs 0 Mi 0	
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device? 1. Yes 2. No N/A		77. Was EOT Device Properly Armed? 1. Yes 2. No N/A	
Fatal 0		0		0		0		78. Caboose Occupied by Crew? 1. Yes 2. No		N/A	
Nonfatal 0		0		0		0					
Highway User Involved						Rail Equipment Involved					
79. Type C. Truck-Trailer. F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)		Code N/A		83. Equipment 3. Train (standing) 6. Light Loco(s) (moving) 1. Train(units pulling) 4. Car(s) (moving) 7. Light(s) (standing) 2. Train(units pushing) 5. Car(s) (standing) 8. Other (specify in narrative)		Code N/A					
80. Vehicle Speed (est. MPH at impact) N/A		81. Direction geographical 1. North 2. South 3. East 4. West		Code N/A		84. Position of Car Unit in Train N/A					
82. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped		Code N/A		85. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User		Code N/A					
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither		Code N/A		86b. Was there a hazardous materials release by 1. Highway User 2. Rail Equipment 3. Both 4. Neither		Code N/A					
86c. State here the name and quantity of the hazardous materials released, if any. N/A											
87. Type of Crossing 1. Gates 4. Wig Wags 7. Crossbucks 10. Flagged by crew 2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other (spec. in narr.) Warning 3. Standard FLS 6. Audible 9. Watchman 12. None		Code N/A		88. Signaled Crossing Warning (See instructions for codes)		Code N/A		89. Whistle Ban 1. Yes 2. No 3. Unknown		Code N/A	
90. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach		Code N/A		91. Crossing Warning Interconnected with Highway Signals 1. Yes 2. No 3. Unknown		Code N/A		92. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown		Code N/A	
93. Driver's Age 0		94. Driver's Gender 1. Male 2. Female Code N/A		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown Code N/A		96. Driver 1. Drove around or thru the Gate 4. Stopped on Crossing 2. Stopped and then Proceeded 5. Other (specify in narrative) 3. Did not Stop Code N/A					
97. Driver Passed Standing Highway Vehicle 1. Yes 2. No 3. Unknown		Code N/A		98. View of Track Obscured by (primary obstruction) 1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative) 2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed		Code N/A					
101. Casualties to Highway-Rail Crossing Users		Killed 0		Injured 0		99. Driver Was 1. Killed 2. Injured 3. Uninjured Code N/A		100. Was Driver in the Vehicle? 1. Yes 2. No		Code N/A	
						102. Highway Vehicle Property Damage (est. dollar damage) 0		103. Total Number of Highway-Rail Crossing Users (include driver) 0			
104. Locomotive Auxiliary Lights? 1. Yes 2. No		Code N/A		105. Locomotive Auxiliary Lights Operational? 1. Yes 2. No		Code N/A					
106. Locomotive Headlight Illuminated? 1. Yes 2. No		Code N/A		107. Locomotive Audible Warning Sounded? 1. Yes 2. No		Code N/A					

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

HQ-
31_Sketch
Statement.
jpg

Regarding Sketch for HQ-31-2005:

Due to severe weather (snow storm) the interstate highway was closed for 36 hours, which prevented the FRA from getting to the accident site before the derailment was cleared. See Attachment, BNSF Derailment Sheet for sketch of the accident area.

109. SYNOPSIS OF THE ACCIDENT

A northbound BNSF freight train derailed south of Southern Junction, 4 miles south of Pueblo, Colorado, on April 9, 2005, at 11:50 p.m. MDT. The accident occurred at BNSF Milepost 122.0, on the Spanish Peak Subdivision of the Powder River Division.

There were 2 locomotives and 26 cars derailed. Four hazmat cars were derailed, up-right and not compromised. There were no injuries related to the incident, no hazardous material involved, and no evacuation was necessary.

At the time of the accident, the weather was clear and windy. The temperature was 53 °F. The total estimated damage is approximately \$528,438.

The probable cause of this accident was a broken wheel; resulting from a pre-existing fracture through the wheel hub of the left No. 5 wheel, on Locomotive No. CSXT 4786.

110. NARRATIVE

The following information was obtained from an investigation that was conducted by the Federal Railroad Administration.

Circumstances Prior to the Accident

The crew of Train Symbol M-SLADEN1-07 included a locomotive engineer, a conductor, and brakeman. They first went on duty at 4:30 p.m., MDT, April 9, 2005, at the Trinidad Terminal, in Trinidad, Colorado. This was the home terminal for all crew members, and all received more than the statutory off duty period, prior to reporting for duty.

Their assigned freight train consisted of four locomotives, one being moved under the requirements of 49 CFR Part 229.9 (noncomplying conditions), with 49 loads and 4 empties. It was 3,189 feet in length, and weighed 6,286 tons. The train departed Trinidad and was scheduled to travel to Denver, Colorado. The train received the required train air brake test, and departed Trinidad Yard at 5:59 p.m.

As the northbound train approached the accident area, the locomotive engineer was seated at the controls on the east side of the leading locomotive, No. BNSF 4496. The conductor was positioned on the west side and the head brakeman was seated in the center of the cab of the leading locomotive.

In the area of the railroad where the accident occurred there is a tangent main line track running through a cut, with dirt banks and drainage ditches on both sides. The grade at this location is a 0.50 percent descending grade and played no part in the derailment.

The railroad timetable direction was north. The geographic direction was northeast. Timetable directions are used throughout this report.

The Accident

The train was leaving a 10-mph speed restriction and was being operated between 8 and 12 mph approaching the accident area. At the time the accident occurred, the train was being operated at 12 mph. The maximum authorized speed at this location is 20 mph, as designated in the current BNSF Timetable No. 6 in effect April 28, 2004. Both speeds were recorded by the event recorder of the controlling Locomotive No. BNSF 4496. The train crew indicated that they felt a violent bump when the third and fourth locomotives and 26 cars in the train derailed. The engineer then looked to the rear of the train and discovered the cars and locomotives were dragging upright and off the track. Shortly thereafter, the train went into an emergency train air brake application. It was later discovered that the left No. 5 wheel hub on the third locomotive, No. CSXT 4786, had broken.

Analysis and Conclusions

Analysis

The BNSF Railway conducted an examination of the wheel set at their test research and development laboratory in Topeka, Kansas. Examination of the wheel set revealed a pre-existing fracture of the left No. 5 wheel hub. This fracture originated at the outer corner of the hub and progressed to the depth of approximately 2 3/4 inches. The presence of such a fracture would significantly reduce the clamping force of the wheel hub on the axle.

Conclusion

The railroad was in compliance with their own, and all applicable Federal standards. There is no indication that this defect could have been detected during the installation of the wheel or during routine locomotive inspections.

Probable Cause & Contributing Factor

The FRA determined that the probable cause of this accident was a broken wheel; resulting from a pre-existing fracture through the wheel hub of the left No. 5 wheel, on Locomotive No. CSXT 4786.