



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2005-34***

***Union Pacific (UP)
Solon Springs, Wisconsin
April 14, 2005***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP]			1a. Alphabetic Code UP			1b. Railroad Accident/Incident No. 0405TC007		
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A			2b. Railroad Accident/Incident N/A		
3. Name of Railroad Responsible for Track Maintenance: Canadian National			3a. Alphabetic Code CN			3b. Railroad Accident/Incident No. 357707		
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month Day Year 04 14 2005			6. Time of Accident/Incident 03:18:00 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM		
7. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision			4. Side collision 5. Raking collision 6. Broken Train collision		
			7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction			10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts		
			13. Other (describe in narrative)			01		
8. Cars Carrying HAZMAT 5		9. HAZMAT Cars Damaged/Derailed 1		10. Cars Releasing HAZMAT 0		11. People Evacuated 120		12. Division TWIN CITIES
13. Nearest City/Town SOLON SPRINGS			14. Milepost (to nearest tenth) 427.8		15. State Abbr Code N/A WI		16. County DOUGLAS	
17. Temperature (F) (specify if minus) 56 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1		
21. Track Name/Number SINGLE MAIN TRACK			22. FRA Track Code Class (1-9, X) 4		23. Annual Track Density (gross tons in millions) 31		24. Time Table Direction Code 1. North 3. East 2	
OPERATING TRAIN #1								
25. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars		
			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car			A. Spec. MoW Equip. Code 1		26. Was Equipment Attended? 1. Yes 2. No 1
								27. Train Number/Symbol MITPR 14
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 44 MPH R			30. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking			g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		
29. Trailing Tons (gross tonnage, excluding power units) 6369						m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s)		
						e. N/A N/A N/A N/A		
						30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0		
31. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded (yes/no)	32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.			
(1) First involved (derailed, struck, etc)		N/A	39	yes	Alcohol Drugs N/A N/A			
(2) Causing (if mechanical cause reported)		M505	0	N/A	33. Was this consist transporting passengers? (Y/N) N/A			
34. Locomotive Units		a. Head End	b. Mid Train	c. Rear End	35. Cars		a. Freight	b. Pass.
			d. Manual	e. Remote			c. Freight	d. Pass.
(1) Total in Train		N/A	N/A	N/A	(1) Total in Equipment Consist		N/A	N/A
(2) Total Derailed		N/A	N/A	N/A	(2) Total Derailed		N/A	N/A
36. Equipment Damage This Consist		N/A	37. Track, Signal, Way, & Structure Damage		N/A	38. Primary Cause Code		N/A
						39. Contributing Cause Code		N/A
Number of Crew Members				Length of Time on Duty				
40. Engineer/Operators N/A	41. Firemen N/A	42. Conductors N/A	43. Brakemen N/A	44. Engineer/Operator Hrs N/A Mi N/A		45. Conductor Hrs N/A Mi N/A		
Casualties to:	46. Railroad Employees	47. Train Passengers	48. Other	49. EOT Device? 1. Yes 2. No N/A		50. Was EOT Device Properly Armed? 1. Yes 2. No N/A		
Fatal	N/A	N/A	N/A	51. Caboose Occupied by Crew? 1. Yes 2. No		N/A		
Nonfatal	N/A	N/A	N/A					
OPERATING TRAIN #2								
52. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars		
			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car			A. Spec. MoW Equip. Code N/A		53. Was Equipment Attended? 1. Yes 2. No N/A
								54. Train Number/Symbol N/A
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A			57. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control			g. Automatic block h. Current of traffic m. Special instructions n. Other than main track		
						57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable		

56. Trailing Tons (gross tonnage, excluding power units) 0		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A			
58. Principal Car/Unit (1) First involved (derailed, struck, etc) 0		a. Initial and Number 0		b. Position in Train 0		c. Loaded(yes/no) N/A		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol N/A Drugs N/A			
(2) Causing (if mechanical cause reported) 0		0		N/A		60. Was this consist transporting passengers? (Y/N) N/A					
61. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote		62. Cars		Loade a. Freight b. Pass. c. Freight d. Pass. e. Caboose	
(1) Total in Train 0		0		0		0		(1) Total in Equipment Consist 0		0	
(2) Total Derailed 0		0		0		0		(2) Total Derailed 0		0	
63. Equipment Damage This Consist 0		64. Track, Signal, Way, & Structure Damage 0		65. Primary Cause Code N/A		66. Contributing Cause Code N/A		Number of Crew Members		Length of Time on Duty	
67. Engineer/Operators 0		68. Firemen 0		69. Conductors 0		70. Brakemen 0		71. Engineer/Operator Hrs 0 Mi 0		72. Conductor Hrs 0 Mi 0	
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device? 1. Yes 2. No N/A		77. Was EOT Device Properly Armed? 1. Yes 2. No N/A	
Fatal 0		0		0		0		78. Caboose Occupied by Crew? 1. Yes 2. No		N/A	
Nonfatal 0		0		0		0					
Highway User Involved						Rail Equipment Involved					
79. Type C. Truck-Trailer. F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)		Code N/A		83. Equipment 3. Train (standing) 6. Light Loco(s) (moving) 1. Train(units pulling) 4. Car(s) (moving) 7. Light(s) (standing) 2. Train(units pushing) 5. Car(s) (standing) 8. Other (specify in narrative)		Code N/A		84. Position of Car Unit in Train 0			
80. Vehicle Speed (est. MPH at impact) 0		81. Direction geographical 1. North 2. South 3. East 4. West		Code N/A		85. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User		Code N/A			
82. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped		Code N/A		86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither		Code N/A		86b. Was there a hazardous materials release by 1. Highway User 2. Rail Equipment 3. Both 4. Neither		Code N/A	
86c. State here the name and quantity of the hazardous materials released, if any. N/A											
87. Type of Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None		Code(s) N/A N/A N/A N/A N/A N/A		88. Signaled Crossing Warning (See instructions for codes)		Code N/A		89. Whistle Ban 1. Yes 2. No 3. Unknown		Code N/A	
90. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach		Code N/A		91. Crossing Warning Interconnected with Highway Signals 1. Yes 2. No 3. Unknown		Code N/A		92. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown		Code N/A	
93. Driver's Age 0		94. Driver's Gender 1. Male 2. Female Code N/A		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown Code N/A		96. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop 4. Stopped on Crossing 5. Other (specify in narrative) Code N/A					
97. Driver Passed Standing Highway Vehicle 1. Yes 2. No 3. Unknown		Code N/A		98. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) Code N/A							
101. Casualties to Highway-Rail Crossing Users		Killed 0		Injured 0		99. Driver Was 1. Killed 2. Injured 3. Uninjured Code N/A		100. Was Driver in the Vehicle? 1. Yes 2. No		Code N/A	
						102. Highway Vehicle Property Damage (est. dollar damage) 0		103. Total Number of Highway-Rail Crossing Users (include driver) 0			
104. Locomotive Auxiliary Lights? 1. Yes 2. No		Code N/A		105. Locomotive Auxiliary Lights Operational? 1. Yes 2. No		Code N/A					
106. Locomotive Headlight Illuminated? 1. Yes 2. No		Code N/A		107. Locomotive Audible Warning Sounded? 1. Yes 2. No		Code N/A					

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

A large, empty rectangular box with a thin black border, occupying most of the page. It is intended for the respondent to draw a sketch of the accident area, including tracks, signals, switches, structures, and objects involved.

109. SYNOPSIS OF THE ACCIDENT

On April 14, 2005, at about 3:18 p.m., Union Pacific (UP) Train No. MITPR-14 with 6369 trailing tons (48 loads, 8 empties) traveling in a southerly direction derailed at mile post 427.8. The train was traveling 44 mph (recorded) at the time of the derailment, authorized track speed is 50 mph (timetable).

Twenty one freight cars derailed including one hazardous material car containing Hexene, (UN 2370) in Tank Car, TILX 301495. The car did not rupture or leak any of the contents. Due to the derailment of the tank car approximately 80 residences were evacuated. The evacuation was conducted by the fire chief of Solon Springs, Wisconsin (WI). There were no injuries to civilian or railroad personnel.

Eight cars containing lumber were on fire after the derailment, the cars were ultimately destroyed, contributing to the evacuation. The weather at the time of the derailment was 56° F and dry.

Of the 21 cars derailed, 18 were destroyed. The total damage to the equipment was \$571,661.00 and \$45,000 damage to track and signal.

The probable cause of this accident was the uncoupling of car CN 623378 (29th car in the consist) and the sequential internal train forces which the uncoupling set-in-motion. The uncoupling resulted due to a missing vertical coupler retaining pin on the a-end coupler shank of car CN 623378.

110. NARRATIVE

Circumstances Prior to the Accident

The train crew for Train No. MITPR-14 consisted of an engineer and conductor, who reported for duty on April 14, 2005, at 10 a.m., CDT.

Prior to reporting for duty, the engineer had 48 hours rest and the conductor had 41 hours rest. The crew members went on duty at Itasca Yard, in Superior, Wisconsin (WI).

The train originated at Itasca Yard and it was the responsibility of the train crew to perform the Class I air brake test on the train.

Train No. MITPR-14 was operating on Wisconsin Central LTD (WC) trackage as it approached Provost Crossing (private) at 44 miles per hour as recorded by the event recorder of the lead locomotive. Authorized track speed is 50 miles per hour as indicated by Canadian National Railroad (CN) timetable No. 2, dated December 12, 2004.

The locomotive engineer was seated on the west side of the lead locomotive (short hood forward) facing south. The conductor was seated on the east side of the locomotive facing south. The conductor stated as lead Locomotive UP 2985 cleared the crossing they felt a rough spot in the rail as the locomotive dipped.

The Accident

Simultaneously, the locomotive engineer made a reduction of the train air brakes. Prior to this, the train air brakes were set to control the speed at a minimum reduction. The locomotive engineer looked into the rear mirror and observed the cars bouncing up and down, it was at this point the train air brakes went into emergency.

When the train came to a complete stop, the conductor walked back to the derailment. This was about 19 cars from the head end and he observed several freight cars on fire. He immediately notified the locomotive engineer of the circumstances who called the dispatcher. The dispatcher called local fire and police departments. Initially, the local fire department received a call from an unknown truck driver who reported a brush fire in the derailment area. It could not be determined if it was direct cause of the derailment. The locomotive engineer and conductor were both alcohol and drug tested under UP reasonable cause. The results were negative for both.

Analysis and Conclusions

On April 14, 2005, prior to departure from Itasca Yard, the locomotives received a daily inspection by the locomotive engineer. The train crew performed a Class I air brake test on the 56 freight cars.

A WC track geometry car tested the rail in November 2004, no exceptions were noted. There were no indications found that track structure was the cause of this derailment.

An inspection of Locomotive UP 2985 revealed it received a daily inspection on April 14, 2005 at 10:40 a.m, at Itasca Yard. The last periodic inspection was conducted on February 11, 2005, at Mt. Vernon, IL.

Locomotive NREX 5066 received a daily inspection on April 14, 2005 at 11:00am, at Itasca Yard. The last periodic inspection was conducted on March 25, 2005, at

Northtown Yard in Minneapolis, MN.

An inspection by FRA, MP&E Inspectors of the locomotives did not reveal any conditions that may have contributed to the derailment. Lead Locomotive UP 2985 had the fuel line safety cut-off device stenciling on the right and left sides of the locomotive missing. Locomotive NREX 5066 had excessive accumulation of water on the cab floor, contributing to a slipping hazard, subject locomotive also had the rear control stand panel missing as it is used only as a trailing locomotive.

An inspection of the derailment site by a FRA track inspector was conducted. The track is 115# continuous welded rail laid in 1999 and ties were replaced in 2000. Mile post 427.84 has a 3 degree 45 minute right hand curve with 3 1/4 inch elevation. Immediately to the north is a 3 degree 19 minute left hand curve with 2 3/4 elevation and to the south a 2 degree 6 minute left hand curve with a 1 1/2 inches elevation. No Track Safety Standard exceptions were observed.

Probable Cause and Contributing Factors

An inspection by Union Pacific mechanical personnel revealed that the vertical coupler retaining pin on the a-end coupler shank of car CN 623378 was missing. The missing pin allowed car CN 623378 to become uncoupled while in transit.

The probable cause of this accident was the uncoupling of car CN 623378 (29th car in the consist) and the sequential internal train forces which the uncoupling set-in-motion. The uncoupling resulted due to a missing vertical coupler retaining pin on the a-end coupler shank of car CN 623378.