



***Federal Railroad Administration  
Office of Safety  
Headquarters Assigned  
Accident Investigation Report  
HQ-2005-82***


***Union Pacific (UP)  
Sibyl, Arizona  
September 25, 2005***

***Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.***

1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP ]			1a. Alphabetic Code UP			1b. Railroad Accident/Incident No. 0905TS014		
2. Name of Railroad Operating Train #2 Union Pacific RR Co. [UP ]			2a. Alphabetic Code UP			2b. Railroad Accident/Incident 0905TS014		
3. Name of Railroad Responsible for Track Maintenance: Union Pacific RR Co. [UP ]			3a. Alphabetic Code UP			3b. Railroad Accident/Incident No. 0905TS014		
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month   Day   Year 09   24   2005			6. Time of Accident/Incident 12:48: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM		
7. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision			4. Side collision 5. Raking collision 6. Broken Train collision		
			7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction			10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts		
						13. Other (describe in narrative)   03		
8. Cars Carrying HAZMAT 5		9. HAZMAT Cars Damaged/Derailed 0		10. Cars Releasing HAZMAT 0		11. People Evacuated 0		12. Division Tucson Service Unit
13. Nearest City/Town Benson			14. Milepost (to nearest tenth) 1047.7		15. State Abbr Code N/A   AZ		16. County COCHISE	
17. Temperature (F) (specify if minus) 70 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1		
21. Track Name/Number Main Track No 1			22. FRA Track Code Class (1-9, X) 3		23. Annual Track Density (gross tons in millions) 39		24. Time Table Direction Code 1. North 3. East 4	
<b>OPERATING TRAIN #1</b>								
25. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars		
			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car			A. Spec. MoW Equip. Code 1		26. Was Equipment Attended? Code 1. Yes 2. No 1
								27. Train Number/Symbol ICXLB-21
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 19 MPH   R			29. Trailing Tons (gross tonnage, excluding power units) 2112			30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits		
						e   N/A   N/A   N/A   N/A		30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter   0
31. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded (yes/no)	32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.			
(1) First involved (derailed, struck, etc)		N/A	1	no	Alcohol		Drugs	
(2) Causing (if mechanical cause reported)		0	0	N/A	0		0	
					33. Was this consist transporting passengers? (Y/N) N			
34. Locomotive Units		a. Head End	b. Mid Train		c. Remote	d. Manual	e. Caboose	35. Cars
(1) Total in Train		2	0	0	0	0	0	(1) Total in Equipment Consist
(2) Total Derailed		0	0	0	0	0	0	(2) Total Derailed
36. Equipment Damage This Consist		2017	37. Track, Signal, Way, & Structure Damage		0	38. Primary Cause Code H605		39. Contributing Cause Code H999
Number of Crew Members					Length of Time on Duty			
40. Engineer/Operators 1		41. Firemen 0	42. Conductors 1	43. Brakemen 0	44. Engineer/Operator Hrs 5 Mi 48			45. Conductor Hrs 5 Mi 48
Casualties to:		46. Railroad Employees	47. Train Passengers	48. Other	49. EOT Device? 1. Yes 2. No   1			50. Was EOT Device Properly Armed? 1. Yes 2. No   1
Fatal		0	0	0				
Nonfatal		N/A	0	0	51. Caboose Occupied by Crew? 1. Yes 2. No			N/A
<b>OPERATING TRAIN #2</b>								
52. Type of Equipment Consist (single entry)			1. Freight train 2. Passenger train 3. Commuter train			4. Work train 5. Single car 6. Cut of cars		
			7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car			A. Spec. MoW Equip. Code 1		53. Was Equipment Attended? Code 1. Yes 2. No 1
								54. Train Number/Symbol IMNLB-21
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH   R			57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable		

56. Trailing Tons ( <i>gross tonnage, excluding power units</i> )		N/A		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other ( <i>Specify in narrative</i> ) Code(s)		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		0					
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.				Alcohol		Drugs			
(1) First involved ( <i>derailed, struck, etc</i> )		DTTB73668		98		yes						N/A		N/A			
(2) Causing ( <i>if mechanical cause reported</i> )		0		N/A		N/A		60. Was this consist transporting passengers? (Y/N)				N/A					
61. Locomotive Units		a. Head End		Mid Train		Rear End		62. Cars		Loaded		Empty		e. Caboose			
				b. Manual		c. Remote				a. Freight		b. Pass.		c. Freight		d. Pass.	
(1) Total in Train		3		0		0		(1) Total in Equipment Consist		95		0		0		0	
(2) Total Derailed		0		0		0		(2) Total Derailed		4		0		0		0	
63. Equipment Damage This Consist		165349		64. Track, Signal, Way, & Structure Damage		5000		65. Primary Cause Code		H605		66. Contributing Cause Code		N/A			
Number of Crew Members				Length of Time on Duty													
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator		72. Conductor							
1		1		1		N/A		Hrs 10 Mi 33		Hrs 10 Mi 33							
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		77. Was EOT Device Properly Armed?							
Fatal		0		0		0		1. Yes 2. No   1		1. Yes 2. No   1							
Nonfatal		1		0		0		78. Caboose Occupied by Crew?		N/A							
								1. Yes 2. No									
Highway User Involved				Rail Equipment Involved													
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle		Code		83. Equipment		3. Train ( <i>standing</i> )		6. Light Loco(s) ( <i>moving</i> )		Code					
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian				N/A		1. Train( <i>units pulling</i> )		4. Car(s)( <i>moving</i> )		7. Light(s) ( <i>standing</i> )		N/A					
B. Truck E. Van H. Motorcycle M. Other ( <i>spec. in narrative</i> )				N/A		2. Train( <i>units pushing</i> )		5. Car(s)( <i>standing</i> )		8. Other ( <i>specify in narrative</i> )		N/A					
80. Vehicle Speed ( <i>est. MPH at impact</i> )		N/A		81. Direction ( <i>geographical</i> )		Code		84. Position of Car Unit in Train				N/A					
				1. North 2. South 3. East 4. West		N/A											
82. Position				Code		85. Circumstance		Code									
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				N/A		1. Rail Equipment Struck Highway User		N/A									
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?				Code		86b. Was there a hazardous materials release by		Code									
1. Highway User 2. Rail Equipment 3. Both 4. Neither				N/A		1. Highway User 2. Rail Equipment 3. Both 4. Neither		N/A									
86c. State here the name and quantity of the hazardous materials released, if any.														N/A			
87. Type of Crossing		1. Gates		4. Wig Wags		7. Crossbucks		10. Flagged by crew		88. Signaled Crossing Warning		Code		89. Whistle Ban		Code	
Warning		2. Cantilever FLS		5. Hwy. traffic signals		8. Stop signs		11. Other ( <i>spec. in narr.</i> )		Code		N/A		1. Yes		Code	
Code(s)		N/A		N/A		N/A		N/A		N/A		N/A		2. No		N/A	
														3. Unknown		N/A	
90. Location of Warning		Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code							
1. Both Sides				1. Yes		N/A		1. Yes		N/A							
2. Side of Vehicle Approach				2. No				2. No									
3. Opposite Side of Vehicle Approach		N/A		3. Unknown				3. Unknown									
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code					
N/A		1. Male		N/A		1. Yes 2. No 3. Unknown		N/A		1. Drove around or thru the Gate		4. Stopped on Crossing					
		2. Female								2. Stopped and then Proceeded		5. Other ( <i>specify in narrative</i> )		N/A			
										3. Did not Stop							
97. Driver Passed Standing Highway Vehicle		Code		98. View of Track Obscured by ( <i>primary obstruction</i> )		Code											
1. Yes 2. No 3. Unknown		N/A		1. Permanent Structure		3. Passing Train		5. Vegetation		7. Other ( <i>specify in narrative</i> )		N/A					
				2. Standing Railroad Equipment		4. Topography		6. Highway Vehicle		8. Not obstructed		N/A					
101. Casualties to Highway-Rail Crossing Users		Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code					
		N/A		N/A		1. Killed 2. Injured 3. Uninjured		N/A		1. Yes		2. No		N/A			
						102. Highway Vehicle Property Damage ( <i>est. dollar damage</i> )		N/A		103. Total Number of Highway-Rail Crossing Users ( <i>include driver</i> )		N/A					
104. Locomotive Auxiliary Lights?						Code		105. Locomotive Auxiliary Lights Operational?		Code							
1. Yes 2. No						N/A		1. Yes 2. No		N/A							
106. Locomotive Headlight Illuminated?						Code		107. Locomotive Audible Warning Sounded?		Code							
1. Yes 2. No						N/A		1. Yes 2. No		N/A							

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.  
HQ-82-2005.jpg



## 109. SYNOPSIS OF THE ACCIDENT

The accident was a rear end collision between two westbound Union Pacific Railroad trains that occurred on September 25, 2005, at approximately 12:48 a.m., Mountain Daylight Time. The point of derailment was at MP 1047.7, on Main Track No. 1, located on the Lordsburg Subdivision of the Tucson Service Unit. The Tucson Service Unit is part of UP's Sunset Area Timetable dated March 7, 2004. Both trains were made up of articulated and conventional inter-modal type freight equipment. In the state of Arizona, Union Pacific observes the Mountain Daylight Time Zone. At the time of the accident it was clear and dark with an ambient temperature of 70 degrees.

The rear end collision caused four well platforms of articulated and conventional equipment to derail. Four well platforms of the 88th through 91st rear platforms (one three platform articulated car and one platform of the following car) to derail on stopped train IMNLB-2 (Train 2). No other equipment derailed. Estimated damages were \$167,366.00 for equipment, \$5,000.00 in track damage and no signal damage. No hazardous materials were spilled nor was there a release of such materials.

The conductor of stopped Train 2 was injured in the collision. He was taken to a hospital where he was treated and released after x-rays were taken, he received an injection and was given a prescription for muscular pain relief in his lower back. No other injuries were reported.

The accident occurred approximately 16 miles east of Benson, Arizona where there are a series of left hand and right hand curves which range between 4 and 7 degrees. In this area, the grade is descending westward at between 0.7 and 1.0 percent.

Probable cause was failure to observe and comply with restricted speed. As a contributing factor the crew of Train 1 failed to observe and comply with instructions of "Cab Red Zone" (CRZ) as defined by UP System Special Instructions dated April 3, 2005, Item 10-A, C.

## 110. NARRATIVE

From the east, approaching the accident site, there is a 6-degree right hand curve, followed by a tangent segment approximately 950 feet long, and a left hand 6-degree curve. Signal 1047.9 is located at Milepost 1047.9 approximately 200 feet west of Milepost 1048 on the tangent track between the two 6-degree curves. The point of collision occurred at a point near the west end of the left-hand curve on a descending 0.75 degree grade. The distance from Signal 1047.9 in a westward direction to the point of collision is approximately 1605 feet.

## THE ACCIDENT:

Train 1 proceeded westbound following Train 2. The conductor was seated on the left hand side of the cab in the conductor's seat. The engineer was seated at the controls of the locomotive on the right hand side of the cab. The crew of the train observed a Stop and Proceed signal aspect (GCOR Rule 9.2.14) displayed at block signal 1047.9 on Main track 1. The engineer brought the train to a stop 275 feet east of the block signal. After stopping, the crew made a decision to proceed further west to determine what was taking place ahead of their train and traveled westbound an additional 1883 feet. At 12:48 a.m., Train 1 struck standing Train 2 at a recorded speed of 19 mph at MP 1047.7, on main track No.1. The first car struck was DTTA 73668, a five platform articulate well car. The collision caused platform DTTB 73668 and all three platforms of a three platform articulated well car, DTTA 620171 to derail (A-C-B platforms). The articulated well cars were the 88th through 91st rear platforms. No cars or locomotives of Train 1 derailed. No hazardous materials cars were derailed and no evacuation was necessary.

Shortly after impact, an Eastbound train was approaching the location of the head end of Train 2.

The crew of Train 2 contacted the Eastbound train and advised what had taken place and to pass their train at restricted speed looking out for equipment fouling Main track 2. At about the same time, the crew of Train 1 advised the crew of Train 2 that their train had just struck the rear car of Train 2. The Crews of both trains notified the train dispatcher of the accident.

The conductor of Train 2 was injured when the train lunged forward after being struck. The conductor felt his lower back stiffen up after he realized what had taken place. As he walked to the rear of his train to make a

determination of damages, his back began to hurt. After making an assessment of damages and securing hand brakes on the train, the conductor reported his lower back began to hurt and asked to be taken to a hospital. A UP officer then drove the conductor to a location where a company provided van could be reached. He was then transported to Northwest Medical Center Hospital in Tucson. At the hospital the conductor had x-rays taken, was given an injection of Toradol, and a prescription for Lodine, medications to relieve pain. The conductor of Train 1 admitted to reading a book during the Cab Red Zone that was called for as the train was presumably proceeding at restricted speed. The engineer of Train 1 stated he was distracted while operating the train after making the stop at block signal 1047.9. He stated he was preoccupied with determining what speed the train was traveling, by looking down at the ground. He said he was trying to determine if the speed indicator was operating properly.

Main track 1 was restored to service on September 26, 2005 at 2:00 p.m.

The conductor and engineer of Train 1 were taken for Post-Accident Toxicological testing at a medical facility and the results were negative for both employees.

UP removed the speed indicator, model 18092, from locomotive UP 4038, Train 1 and shipped it to Wabtec, an independent contract laboratory, to be analyzed for accuracy. One speed indicator was removed from the locomotive engineer's side and one from the conductor's side of the locomotive. The results of testing for serial number 0285250, on the ½ scale, the unit is high by 1 mile, full scale it is low by 2 miles. Wabtec recommends that particular unit needs calibration. The results of testing for serial number 0318696, on the ½ scale, the unit is high by 2 miles, full scale the unit is on the mark at 82.5. All measurements were within FRA compliance limits.

#### ANALYSIS AND CONCLUSIONS:

The event recorder from locomotive UP 4038 was downloaded as soon as practicable following the collision. The download revealed Train 1 was traveling at a speed of 19 MPH when it struck the rear car of Train 2. It also revealed the engineer, despite the fact the train was on between a 0.7% and 1% descending grade, operated up to throttle position 3, to move the train from a stop. After bringing the throttle back to idle and going into dynamic braking, the engineer then made a 6 pound brake pipe reduction on the automatic brake valve, which was rapidly followed by an emergency application of the train brakes. Additionally, the engineer made a 30 pound application on the independent brake valve. The engineer then fully released the independent brake, as the application of the independent brake would nullify the retarding force of the dynamic brakes.

Testimony from the company held investigation revealed the engineer did not comply with restricted speed and neither the conductor nor the engineer was in compliance with the requirements of a Cab Red Zone (CRZ) situation.

In addition, UP and FRA interviews with both the conductor and the engineer noted similar results, in that, a failure to comply with restricted speed as well as the requirements of CRZ was evident.

Work histories for both the conductor and the engineer of Train 1 noted both had sufficient off-duty periods prior to reporting for duty on September 24, 2005.

The locomotive engineer of Train 1 had just recently returned to service following a major rules infraction. The engineer was out of service following a STOP signal violation at CP 988 in Tucson, Arizona on July 1, 2005. The engineer was operating train ZMQLA-30 and was unable to stop his train before passing the signal displaying STOP. He was removed from service and de-certified for 30 days. Following his return to service the engineer was set back to student engineer status and was required to complete remedial training. He was required to make four trips with a certified locomotive engineer while in student status and was also required to pass a monitored simulator trip.

The engineer did complete remedial training with a passing grade and was return to active duty.

A review of UP operational testing records for the conductor of Train 1 did not reveal any red block test failures prior to this accident.

At FRA's request, the speed indicator was shipped to an independent contract laboratory to determine the accuracy of the device. Results indicate one of the speed indicators needed to be recalibrated however they both were within FRA compliance limits.

#### PROBABLE CAUSE AND CONTRIBUTING FACTORS:

Probable cause was failure to observe and comply with restricted speed. As a contributing factor the crew of Train 1 failed to observe and comply with instructions of "Cab Red Zone" (CRZ) as defined by UP System Special Instructions dated April 3, 2005, Item 10-A, C-1. The FRA concurs with these findings.

Examination of the speed indicator determined it was not a casual factor.

#### APPLICABLE RULES

Restricted speed as defined by GCOR rule 6.27 reads in part: When required to move at restricted speed, movement must be made at a speed that allows stopping within half the range of vision short of: train, engine, railroad car, men or equipment fouling the track, Stop signal or derail or switch not properly lined. When a train

or engine is required to move at restricted speed, the crew must keep a lookout for broken rail and not exceed 20 mph.

Cab Red Zone instructions require crews to act responsibly when operating at restricted speed. The instructions read in part: During "CRZ" an environment must be created in the control compartment that focuses exclusively on controlling the train and complying with the rules.

#