



***Federal Railroad Administration  
Office of Safety  
Headquarters Assigned  
Accident Investigation Report  
HQ-2005-94***


***Union Pacific (UP)  
Lorraine, Wyoming  
October 24, 2005***

***Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.***

1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP ]			1a. Alphabetic Code UP			1b. Railroad Accident/Incident No. 1005FW029		
2. Name of Railroad Operating Train #2 Union Pacific RR Co. [UP ]			2a. Alphabetic Code UP			2b. Railroad Accident/Incident 1005FW029		
3. Name of Railroad Responsible for Track Maintenance: Union Pacific RR Co. [UP ]			3a. Alphabetic Code UP			3b. Railroad Accident/Incident No. 1005FW029		
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month   Day   Year 10   24   2005			6. Time of Accident/Incident 06:44: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM		
7. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision			4. Side collision 5. Raking collision 6. Broken Train collision		
			7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction			10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts		
			13. Other (describe in narrative)			03		
8. Cars Carrying HAZMAT 7		9. HAZMAT Cars Damaged/Derailed 0		10. Cars Releasing HAZMAT 0		11. People Evacuated 0		12. Division Fort Worth
13. Nearest City/Town Loraine			14. Milepost (to nearest tenth) 465.7		15. State Abbr Code N/A   TX		16. County MITCHELL	
17. Temperature (F) (specify if minus) 70 F		18. Visibility (single entry) 1. Dawn 3. Dusk 2. Day 4. Dark		Code 2		19. Weather (single entry) 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow		Code 1
20. Type of Track 1. Main 3. Siding 2. Yard 4. Industry			Code 1					
21. Track Name/Number Main Track			22. FRA Track Code Class (1-9, X) 5		23. Annual Track Density (gross tons in millions) 35		24. Time Table Direction 1. North 3. East Code 4	
<b>OPERATING TRAIN #1</b>								
25. Type of Equipment Consist (single entry)			1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car			A. Spec. MoW Equip. Code 1		26. Was Equipment Attended? 1. Yes 2. No   1
27. Train Number/Symbol KCXCI-22								
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 18 MPH   R			30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits			30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter   0		
29. Trailing Tons (gross tonnage, excluding power units) 4735								
31. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded (yes/no)	32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.			
(1) First involved (derailed, struck, etc)		N/A	1	no	Alcohol		Drugs	
(2) Causing (if mechanical cause reported)		0	0	N/A	0		0	
					33. Was this consist transporting passengers? (Y/N) N			
34. Locomotive Units		a. Head End	b. Mid Train	c. Rear End	35. Cars		a. Freight	b. Pass.
		d. Manual	e. Remote				c. Freight	d. Pass.
		e. Caboose						
(1) Total in Train		2	0	0	(1) Total in Equipment Consist		78	0
(2) Total Derailed		0	0	0	(2) Total Derailed		0	0
		0	0	0			0	0
36. Equipment Damage This Consist		0	37. Track, Signal, Way, & Structure Damage 700		38. Primary Cause Code H605		39. Contributing Cause Code N/A	
Number of Crew Members				Length of Time on Duty				
40. Engineer/Operators 1		41. Firemen 0	42. Conductors 1	43. Brakemen 0	44. Engineer/Operator Hrs 0 Mi 44		45. Conductor Hrs 0 Mi 44	
Casualties to:		46. Railroad Employees	47. Train Passengers	48. Other	49. EOT Device? 1. Yes 2. No   1		50. Was EOT Device Properly Armed? 1. Yes 2. No   1	
Fatal		0	0	0				
Nonfatal		N/A	0	0	51. Caboose Occupied by Crew? 1. Yes 2. No		2	
<b>OPERATING TRAIN #2</b>								
52. Type of Equipment Consist (single entry)			1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car			A. Spec. MoW Equip. Code 1		53. Was Equipment Attended? 1. Yes 2. No   1
54. Train Number/Symbol IMNLB 22								
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH   R			57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable		

56. Trailing Tons ( <i>gross tonnage, excluding power units</i> )		4617		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other ( <i>Specify in narrative</i> ) Code(s)		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		0					
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.				Alcohol		Drugs			
(1) First involved ( <i>derailed, struck, etc</i> )		DDTB427018		80		no						0		0			
(2) Causing ( <i>if mechanical cause reported</i> )		0		0		N/A		60. Was this consist transporting passengers? (Y/N)						N			
61. Locomotive Units		a. Head End		Mid Train		Rear End		62. Cars		Loaded		Empty		e. Caboose			
				b. Manual		c. Remote				a. Freight		b. Pass.		c. Freight		d. Pass.	
(1) Total in Train		3		0		0		(1) Total in Equipment Consist		9		0		9		0	
(2) Total Derailed		0		0		0		(2) Total Derailed		0		0		4		0	
63. Equipment Damage This Consist		50539		64. Track, Signal, Way, & Structure Damage		0		65. Primary Cause Code		H605		66. Contributing Cause Code		N/A			
Number of Crew Members				Length of Time on Duty													
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator		72. Conductor							
1		0		1		0		Hrs 1 Mi 24		Hrs 1 Mi 24							
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		77. Was EOT Device Properly Armed?							
Fatal		0		0		0		1. Yes 2. No   1		1. Yes 2. No   1							
Nonfatal		0		0		0		78. Caboose Occupied by Crew?		79. Was Caboose Occupied by Crew?						2	
								1. Yes 2. No		1. Yes 2. No							
Highway User Involved				Rail Equipment Involved													
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle		Code		83. Equipment		3. Train ( <i>standing</i> )		6. Light Loco(s) ( <i>moving</i> )		Code					
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian				N/A		1. Train( <i>units pulling</i> )		4. Car(s)( <i>moving</i> )		7. Light(s) ( <i>standing</i> )		N/A					
B. Truck E. Van H. Motorcycle M. Other ( <i>spec. in narrative</i> )				N/A		2. Train( <i>units pushing</i> )		5. Car(s)( <i>standing</i> )		8. Other ( <i>specify in narrative</i> )		N/A					
80. Vehicle Speed ( <i>est. MPH at impact</i> )		N/A		81. Direction ( <i>geographical</i> )		Code		84. Position of Car Unit in Train		N/A							
				1. North 2. South 3. East 4. West		N/A											
82. Position		1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped		Code		N/A		85. Circumstance		1. Rail Equipment Struck Highway User		Code		2. Rail Equipment Struck by Highway User		N/A	
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?		Code		N/A		86b. Was there a hazardous materials release by		Code		1. Highway User 2. Rail Equipment 3. Both 4. Neither		N/A					
1. Highway User 2. Rail Equipment 3. Both 4. Neither		N/A															
86c. State here the name and quantity of the hazardous materials released, if any.														N/A			
87. Type of Crossing Warning		1. Gates 4. Wig Wags 7. Crossbucks 10. Flagged by crew		88. Signaled Crossing Warning		Code		89. Whistle Ban		Code							
2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other ( <i>spec. in narr.</i> )		3. Standard FLS 6. Audible 9. Watchman 12. None		(See instructions for codes)		N/A		1. Yes 2. No 3. Unknown		N/A							
Code(s)		N/A		N/A		N/A		N/A		N/A							
90. Location of Warning		Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code							
1. Both Sides				1. Yes 2. No 3. Unknown		N/A		1. Yes 2. No 3. Unknown		N/A							
2. Side of Vehicle Approach																	
3. Opposite Side of Vehicle Approach		N/A															
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code					
0		1. Male 2. Female		N/A		1. Yes 2. No 3. Unknown		N/A		1. Drove around or thru the Gate 4. Stopped on Crossing 2. Stopped and then Proceeded 5. Other ( <i>specify in narrative</i> )		N/A					
97. Driver Passed Standing Highway Vehicle		Code		98. View of Track Obscured by ( <i>primary obstruction</i> )		Code		N/A		100. Was Driver in the Vehicle?		Code					
1. Yes 2. No 3. Unknown		N/A		1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other ( <i>specify in narrative</i> )		N/A				1. Yes 2. No		N/A					
101. Casualties to Highway-Rail Crossing Users		Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code					
		0		0		1. Killed 2. Injured 3. Uninjured		N/A		1. Yes 2. No		N/A					
104. Locomotive Auxiliary Lights?		Code		105. Locomotive Auxiliary Lights Operational?		Code											
1. Yes 2. No		N/A		1. Yes 2. No		N/A											
106. Locomotive Headlight Illuminated?		Code		107. Locomotive Audible Warning Sounded?		Code											
1. Yes 2. No		N/A		1. Yes 2. No		N/A											

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.  
HRX-94-  
2005.jpg



109. SYNOPSIS OF THE ACCIDENT

Union Pacific train KCXCI-22, was traveling west bound on the main track Toyah subdivision, under a restricting signal at approximately 18 mph. Union Pacific train IMNLB-22 was stopped on the main track between switches at Loraine, TX. As the crew of KCXCI-22 approached the rear of the IMNLB-22, they applied an emergency application of the train brakes, approximately 5 cars prior to impact. Union Pacific train IMNLB-22 had several empty intermodal cars on rear of their consist. Due to possibility of the setting sun in their eyes, the crew of the KCXCI-22 alleges they did not see the actual end of the train but rather a loaded intermodal car a head of the empties. The rear-end impact collision resulted in several cars on the IMNLB-22 to derail and impact the side of a 3rd train, east bound IGSMN4-20, which had entered the siding at Loraine.

This occurred on October 24, 2005 at approximately 6:44 PM CST. The weather was clear, daylight, and 70 degrees. Location of the accident occurred at Loraine siding, mile post 465.7. Loraine siding is located in the city of Loraine, TX where highway 20 and Main street intersect.

There were no fatalities or known injuries.

A total of 11 cars were damaged, 4 of which derailed, with estimated damages at approximately \$55,809.73 for rail car damage and track work, not including clearing cost of \$34,700.00.

110. NARRATIVE

INFORMATION PROVIDED ON OPERATING TRAIN # 3:

OPERATING TRAIN #3

25. Type of Equipment	1. Freight Train	4. Work Train	7. Yard/switching	A. Spec. MofW
Equip. 26. Was Equipment	Code	27. Train Number/Symbol		
Consist (single entry)	2. Passenger Train	5. Single Car	8. Light loco(s)	
Code Attended?	IGSMN4 20			
3. Commuter Train	6. Cut of cars	9. Maint./inspect. car	1	1. Yes 2. No
1				
28. Speed (recorded speed, if available)	Code	30. Method(s) of Operation	(enter code(s) that apply)	
30a. Remotely Controlled Locomotive?				
R - Recorded	02 MPH	E	a. ATCS	g. Automatic block m.
Special instructions				
0 = Not a remotely controlled operation				
E - Estimated		b. Auto train control	h. Current of traffic	n.
Other than main track	1 = Remote control portable transmitter			
29. Trailing Tons (gross tonnage,		c. Auto train stop	i. Time table/train orders	o.
Positive train control	2 = Remote control tower operation			
excluding power units)		d. Cab signals	j. Track warrant control	p. Other (specify in
narrative)	3 = Remote control portable			transmitter -
3550	e. Traffic control	k. Direct traffic control	Codes (s)	
more than one Code				
	f. Interlocking	l. Yard limits	G	J
remote control transmitter	0			
31. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded (yes/no)	32. If
railroad employee(s) tested for drug/alcohol use,				

(1) First involved

(derailed, struck, etc.) DTTA 27434 10 YES enter the number that were positive  
Alcohol Drugs in the appropriate box. 0 0  
(2) Causing (if mechanical, cause reported) N/A N/A N/A 33. Was this consist transporting passengers? (Y/N)  
N  
34. Locomotive Units a. HeadEnd Mid Train Rear End 35. Cars Loaded  
Empty e. Caboose  
b. Manual c. Remote  
d. Manual e. Remote a. Freight b. Pass. a. Freight b. Pass.  
(1) Total in Train 2 0 0 0 0 (1) Total in Equip.  
Consist 62 0 0 0 0  
(2) Total Derailed 0 0 0 0 0 (2) Total Derailed 0 0  
0 0 0

36. Equipment Damage  
This Consist 37. Track, Signal, Way, & Structure Damage 38.  
Primary Cause Code 39. Contributing Cause Code  
5270 0 H605 N/A  
Number of Crew Members Length of Time on Duty  
40. Engineers/ Operators 41. Firemen 42. Conductors 43. Brakemen 44.  
Engineer/Operator 45. Conductor  
1 0 1 0 Hrs: 9 Mins: 9 Hrs: 9 Mins: 9  
Casualties to: 46. Railroad Employees 47. Train Passengers 48. Others 49. EOT  
Device? 50. Was EOT Device Properly Armed?  
Fatal 0 0 0 1. Yes 2. No 1 1. Yes 2. No 1  
Nonfatal 0 0 0 51. Caboose Occupied by Crew? 1. Yes 2. No 2

The following was obtained from an investigation that was performed by the Federal Railroad Administration.

CIRCUMSTANCES PRIOR TO THE ACCIDENT

KCXCI 22 West

The engineer and conductor of the KCXCI 22, reported for duty on October 24, 2005 at 6:00 PM, at Sweetwater, TX. This was the home terminal for the crew, and all received more than the statutory off duty period, prior to reporting for duty. The KCXCI 22, freight train, departed terminal at approximately 6:05 PM and headed west toward Pecos, TX with a track warrant to Loraine siding hold the main. The maximum speed was 50 MPH unless restricted in the current UP Sunset Area time table # 1.

As the westbound train approached the accident area, the locomotive engineer was seated at the controls on the north side of the leading locomotive watching out and observing signals ahead. The conductor was seated on the south side of the leading locomotive watching out, observing signals, calling out signals, maintaining signal log book, and monitoring the radio.

In this area of the railroad there are, in succession, a 10 degree curve to the right of about 1400 feet, followed by a tangent of about 2200 feet to the point of the accident. There is a 0.7 percent degree descending grade. In this area of Interstate Highway 20, which goes over the tracks, the tracks continue straight west for about 2,200 feet to the first crossing and another 2,000 feet to the second crossing and then continues on west adjacent to Interstate Highway 20 for a considerable distance beyond.

The railroad timetable direction of the train was west. The geographic direction was southwest. Timetable directions are used throughout this report.

IMNLB 22 West

The engineer and conductor of the IMNLB 22, reported for duty on October 24, 2005 at 5:20 PM, at Sweetwater, TX. This was the home terminal for the crew, and all received more than the statutory off duty period, prior to reporting for duty. The IMNLB 22, freight train, departed terminal at approximately 5:30 PM and headed west toward Pecos, TX.

IGSMN4 20 East

The engineer and conductor of the IGSMN4 20, reported for duty on October 24, 2005 at 9:35 AM, at Pecos, TX. This was the away from home terminal for the crew, and all received more than the statutory off duty period, prior to reporting for duty. The IGSMN4 20, freight train, departed terminal at approximately 1000 AM and headed east toward Sweetwater, TX

THE ACCIDENT

**KCXCI 22 West**

As the train passed the west end of Roscoe siding the train began running on approach signals and then at east end of Loraine passed a restricted signal at 18 MPH. At approximately 6:44 PM the train passed the east end of Loraine, MP 465.7, where the crew was unable to see the rear end of IMNLB 22, due to the possible glare of the sun, and as a result the train impacted the rear end car, 97th car, of IMNLB 22 at 13 MPH. The speeds were recorded by the event recorder of the controlling locomotive.

**IMNLB 22 West**

Upon arrival at Loraine siding, approximately 6:35 PM, IMNLB 22 remained on the main track and pulled down to west end where the conductor lined the switch for an east bound train, IGSMN4 20. At approximately 6:44 PM, after IGSMN4 20 had been lined into the siding and west switch restored for the main, the crew on IMNLB 22 felt the impact from KCXCI 22 resulting in 4 cars derailing, cars 80 thru 83, into IGSMN4 20, damaging 7 cars.

**IGSMN4 20 East**

At approximately 6:40 PM upon arrival at Loraine siding the IGSMN4 20 was lined into the siding by the conductor, of the IMNLB 22, to meet two west bound trains. At approximately 6:43 PM IGSMN4 20 pulled down to east end of Loraine siding to await the second train, KCXCI 22, presently pulling up to east end of Loraine siding. At approximately 6:44 PM KCXCI 22 passed east end of Loraine siding and misjudged the rear end of the IMNLB 22 and placed train into emergency several seconds before impacting rear end of the train at approximately 200 feet past east switch of Loraine siding, MP 465.7.

**ANALYSIS**

The south bound train, KCXCI 22, with engineer and conductor on board failed to comply with restricted speed on the Toyah subdivision in track warrant, ABS, territory. The post-accident toxicological test performed on the engineer and conductor, of the KCXCI 22, were performed by the UP railroad, due to accident/incident was non qualifying for FRA. The results of the test, both alcohol and drug, performed by UP railroad showed negative for both crew members. No evaluation and testing of lead locomotive, of the KCXCI 22, were performed by UP railroad, except download and analysis of recorder data. The train, KCXCI 22, was equipped with a speed indicator and an event recorder as required. The relevant event recorder data was downloaded and analyzed by the manager of train operations at Odessa, TX. The analysis disclosed that the locomotive engineer was not in compliance with railroad operating and train handling requirements of operating train under a restricting signal at restricted speed. The FRA reviewed the results of this analysis, and concurred with the conclusions. Also no FRA test on track or locomotive equipment were done but visual inspection of accident area with photographs of Loraine siding were taken.

**CONCLUSION**

The railroad was not in full compliance with their own standards and regulations when the crew operated KCXCI 22 under a restricted signal at a speed which did not allow them to stop short of train ahead. The train crew members of the KCXCI 22 were the only witnesses to the accident, and they had no information that could be used to determine why the train did not stop short of the train ahead. Based on the evidence the inattention of both the engineer and conductor were predominant factors in the resulting rear-end collision.

**PROBABLE CAUSE AND CONTRIBUTING FACTOR**

The FRA determined the probable cause to be the Failure of the engineer on KCXCI 22 to comply with restricted speed in connection with the restrictive indication of a block or interlocking signal caused the rear-end collision at Loraine TX.