



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2005-96***

***Canadian National (CN)
Cherokee, Iowa
October 27, 2005***


Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Canadian National		1a. Alphabetic Code CN		1b. Railroad Accident/Incident No. 394775	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident N/A	
3. Name of Railroad Responsible for Track Maintenance: N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A	
4. U.S. DOT_AAR Grade Crossing Identification Number		5. Date of Accident/Incident Month: 10, Day: 27, Year: 2005		6. Time of Accident/Incident 12:50:00 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM	
7. Type of Accident/Incident (single entry in code box) 1. Derailment 4. Side collision 7. Hwy-rail crossing 10. Explosion-detonation 13. Other (describe in narrative) 2. Head on collision 5. Raking collision 8. RR grade crossing 11. Fire/violent rupture 3. Rear end collision 6. Broken Train collision 9. Obstruction 12. Other impacts					
8. Cars Carrying HAZMAT 0	9. HAZMAT Cars Damaged/Derailed 0	10. Cars Releasing HAZMAT 0	11. People Evacuated 0	12. Division Chicago	
13. Nearest City/Town Cherokee		14. Milepost (to nearest tenth) 454.5	15. State Abbr Code N/A IA	16. County CHEROKEE	
17. Temperature (F) (specify if minus) 27 F	18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4	19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1	20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1		
21. Track Name/Number Main Track		22. FRA Track Code Class (1-9, X) 3	23. Annual Track Density (gross tons in millions) 4.7	24. Time Table Direction Code 1. North 3. East 3	
OPERATING TRAIN #1					
25. Type of Equipment Consist (single entry) 1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car	
28. Speed (recorded speed, if available) Code R - Recorded 28 MPH E - Estimated		30. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking		30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter	
29. Trailing Tons (gross tonnage, excluding power units) 18486		31. Principal Car/Unit a. Initial and Number N/A b. Position in Train 6 c. Loaded (yes/no) yes		26. Was Equipment Attended? Code 1. Yes 2. No 1	
27. Train Number/Symbol C7789126		32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol: N/A Drugs: N/A		33. Was this consist transporting passengers? (Y/N) N/A	
34. Locomotive Units (1) Total in Train: 2 (2) Total Derailed: 0		35. Cars (1) Total in Equipment Consist: 132 (2) Total Derailed: 21		36. Equipment Damage This Consist: 1000000	
37. Track, Signal, Way, & Structure Damage 3000		38. Primary Cause Code T299		39. Contributing Cause Code N/A	
40. Engineer/Operators 2		41. Firemen 0		42. Conductors 1	
43. Brakemen 0		44. Engineer/Operator Hrs 3		45. Conductor Hrs 3	
46. Railroad Employees 0		47. Train Passengers 0		48. Other 0	
49. EOT Device? 1. Yes 2. No 1		50. Was EOT Device Properly Armed? 1. Yes 2. No 1		51. Caboose Occupied by Crew? 1. Yes 2. No	
OPERATING TRAIN #2					
52. Type of Equipment Consist (single entry) 1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car	
53. Was Equipment Attended? Code 1. Yes 2. No N/A		54. Train Number/Symbol N/A		55. Speed (recorded speed, if available) Code R - Recorded 0 MPH E - Estimated N/A	
57. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control		g. Automatic block h. Current of traffic		m. Special instructions n. Other than main track	
57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable					

56. Trailing Tons (<i>gross tonnage, excluding power units</i>)		N/A		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (<i>Specify in narrative</i>) Code(s)		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		N/A							
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.		Alcohol		Drugs							
(1) First involved (<i>derailed, struck, etc</i>)		0		N/A		N/A				N/A		N/A							
(2) Causing (<i>if mechanical cause reported</i>)		0		N/A		N/A		60. Was this consist transporting passengers? (Y/N)				N/A							
61. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote		62. Cars		Loaded a. Freight b. Pass.		Empty c. Freight d. Pass.		e. Caboose					
(1) Total in Train		0		0 0		0 0		(1) Total in Equipment Consist		0 0		0 0		0 0					
(2) Total Derailed		0		0 0		0 0		(2) Total Derailed		0 0		0 0		0 0					
63. Equipment Damage This Consist		0		64. Track, Signal, Way, & Structure Damage		0		65. Primary Cause Code		N/A		66. Contributing Cause Code		N/A					
Number of Crew Members						Length of Time on Duty													
67. Engineer/Operators		N/A		68. Firemen		N/A		69. Conductors		N/A		70. Brakemen		N/A					
71. Engineer/Operator		Hrs 0 Mi 0		72. Conductor		Hrs 0 Mi 0		76. EOT Device?		1. Yes 2. No N/A		77. Was EOT Device Properly Armed?		1. Yes 2. No N/A					
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		78. Caboose Occupied by Crew?		1. Yes 2. No				N/A					
Fatal		0		0		0													
Nonfatal		0		0		0													
Highway User Involved						Rail Equipment Involved													
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle Code		A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian		B. Truck E. Van H. Motorcycle M. Other (<i>spec. in narrative</i>)		N/A		83. Equipment		3. Train (<i>standing</i>) 6. Light Loco(s) (<i>moving</i>) Code		1. Train(<i>units pulling</i>) 4. Car(s)(<i>moving</i>) 7. Light(s) (<i>standing</i>)		2. Train(<i>units pushing</i>) 5. Car(s)(<i>standing</i>) 8. Other (<i>specify in narrative</i>)		N/A	
80. Vehicle Speed		N/A		81. Direction (<i>geographical</i>)		Code		84. Position of Car Unit in Train		N/A									
(est. MPH at impact)				1. North 2. South 3. East 4. West		N/A													
82. Position		Code		85. Circumstance		Code		1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing		1. Rail Equipment Struck Highway User		2. Rail Equipment Struck by Highway User		N/A					
4. Trapped		N/A																	
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?		Code		86b. Was there a hazardous materials release by		Code		1. Highway User 2. Rail Equipment 3. Both 4. Neither		N/A									
1. Highway User 2. Rail Equipment 3. Both 4. Neither		N/A																	
86c. State here the name and quantity of the hazardous materials released, if any.														N/A					
87. Type of Crossing		1. Gates 4. Wig Wags 7. Crossbucks 10. Flagged by crew		2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other (<i>spec. in narr.</i>)		3. Standard FLS 6. Audible 9. Watchman 12. None		88. Signaled Crossing Warning Code		(See instructions for codes)		89. Whistle Ban Code		1. Yes 2. No 3. Unknown		N/A			
Code(s)		N/A		N/A		N/A		N/A		N/A		N/A							
90. Location of Warning		Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code		1. Both Sides		1. Yes 2. No 3. Unknown					
2. Side of Vehicle Approach		N/A		1. Yes 2. No 3. Unknown		N/A		1. Yes 2. No 3. Unknown		N/A									
3. Opposite Side of Vehicle Approach																			
93. Driver's Age		94. Driver's Gender Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code		1. Drove around or thru the Gate 4. Stopped on Crossing		2. Stopped and then Proceeded 5. Other (<i>specify in narrative</i>)		N/A			
0		1. Male 2. Female N/A		1. Yes 2. No 3. Unknown		N/A		3. Did not Stop		N/A									
97. Driver Passed Standing Highway Vehicle		Code		98. View of Track Obscured by (<i>primary obstruction</i>)		Code		1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (<i>specify in narrative</i>)		2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed		N/A							
1. Yes 2. No 3. Unknown		N/A																	
101. Casualties to Highway-Rail Crossing Users		Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code		1. Killed 2. Injured 3. Uninjured		N/A			
0		0		0		1. Killed 2. Injured 3. Uninjured		N/A		1. Yes 2. No		N/A							
104. Locomotive Auxiliary Lights?		Code		105. Locomotive Auxiliary Lights Operational?		Code		1. Yes 2. No		N/A									
1. Yes 2. No		N/A		1. Yes 2. No		N/A													
106. Locomotive Headlight Illuminated?		Code		107. Locomotive Audible Warning Sounded?		Code		1. Yes 2. No		N/A									
1. Yes 2. No		N/A		1. Yes 2. No		N/A													

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

HQ-96-
2005
sketch.jpg



109. SYNOPSIS OF THE ACCIDENT

AA Chicago Central and Pacific (CC) coal train derailed on October 27, 2005, at 12:50 a.m. The accident occurred near Cherokee, Iowa, at milepost (MP) 454.5, on the CC Cherokee Subdivision. There were no injuries or hazardous material spills as result of the derailment. Monetary damages reported for the derailment totaled \$1,003,000. At the time of the accident, it was dark with clear skies and a temperature of 27 °F. The cause of the derailment is being ruled as a broken rail, although the exact type of break was not determined. An eastbound train was operating on single main track at a recorded speed of 28 mph when the accident occurred. While traversing a right-hand curve, the train experienced an undesired emergency application of the air brake system, where upon it was discovered the 4th through 24th head cars had derailed.

110. NARRATIVE

Circumstances Prior to the Accident

The train crew of Train Symbol C77891-26 consisted of an engineer, student engineer, and conductor. They first went on duty at 9:20 p.m., CST, October 26, 2005, at Sioux City, Iowa. This was their home terminal, and all three had received more than the statutory off duty period prior to reporting for duty.

Their assigned train consisted of 2 locomotives on the head end, 132 loaded coal cars, and a remote unit on the rear end. The train was 7,229 feet long and weighed 18,486 tons. This crew was scheduled to take the train to Fort Dodge, Iowa and be relieved.

There was no work performed en route after departing and the trip was uneventful for the 61 miles leading up to the derailment.

As the eastbound train approached the accident area, the student engineer was seated at the controls on the south side of the lead locomotive. The locomotive engineer and conductor were seated on the north side of the same locomotive.

The track structure through the accident site is in a 2-degree 35-minute curve on a 1percent descending grade. It is constructed of 90-pound continuous welded rail on wood crossties.

The railroad timetable direction and geographical direction of the train are both east.

The Accident

The train was being operated at 28 mph approaching the derailment area. According to the train crew they did not observe or feel anything unusual prior to this area. The speed at the time of the derailment was 28 mph. Both speeds were recorded by the event recorder of the controlling locomotive. Maximum authorized speed for this curve was 30 mph as designated in current CN/IC Chicago Division Timetable.

Analysis and Conclusions

Analysis

Although the final cost of this derailment totaled just over \$1,000,000, making it a major accident, the three crew members of Train Symbol C77891-26 were not FRA mandatory post-accident toxicologically tested. A Chicago Central Road Foreman of Engines was 33 miles away in Storm Lake, Iowa, when the accident

occurred waiting for this crew to ride with them to Ft. Dodge, Iowa. He was on the scene within 45 minutes of the wreck and downloaded the event recorders. The event recorders for both lead locomotives revealed nothing inconsistent with normal train handling at or prior to the time of the derailment. The Road Foreman relayed this information to the CC Assistant Superintendent who was coming from Waterloo, Iowa, some 200 miles away. The Assistant Superintendent, in good faith, determined testing would not be necessary because by not being there he did not realize most of the rail cars were completely destroyed, thus driving the total cost to just over \$1 million.

The last ultra sonic rail detection test through this area was on September 22, 2005, and the last geometry car survey, with the railroad's car, was in April 2005, with no defects noted in the immediate area.

Conclusion

The railroad was in compliance with their own and, all applicable FRA standards. There were no witnesses to the accident, other than the train crew, who only felt a small surge at the time they experienced the undesired emergency application of the air brakes.

Nothing was found at the derailment that could positively be attributed as the cause. The data reviewed from the event recorder ruled out train handling as a cause. There were also no track components, i.e. turnouts, bridges, grade crossings, or culverts at the point of derailment (POD) that could have contributed to the cause. The grade and curvature of the track were not a factor in this derailment for the speed involved.

There were no markings found on any wheels of the equipment that made it over the POD. Likewise there were no marks on the track structure prior to the derailment area, meaning that this derailment happened catastrophically and suddenly. In these cases the likely cause generally points to track or mechanical.

Probable Cause & Contributing Factors

All the truck components and wheels from the derailed cars were recovered with nothing suspicious found, thus ruling out mechanical.

On Monday, October 24, 2005, three days prior to the derailment, local maintenance forces found a fully broken rail on the high side of the curve at this same location. This rail break originated from a detail fracture of approximately 10% in the gage corner and had rapid growth of the defect prior to breaking. The rail was changed that same day and the ends welded. Both welds were found in the derailment and had not failed.

Several broken pieces of rail pulled from the derailment had small fissures on the gage corner. These pieces were all from the rail on the high side of the curve and happened as a result of the derailment and not as the cause. The fissures were all smaller than 5% and were all originating in head checking from the gage corner. Head checking was very evident in the remainder of the curve that was not damaged in the derailment. With this knowledge, the probable cause for this derailment is most likely a broken rail. Since the actual piece that caused the derailment was never found, it is impossible to determine what type defect caused it, but in all likelihood, it was a detail fracture originating in the gage corner from the head checking.