



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2005-108***


***Norfolk Southern (NS)
Reynolds, Georgia
December 22, 2005***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Norfolk Southern Corp. [NS]			1a. Alphabetic Code NS			1b. Railroad Accident/Incident No. 23530			
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A			2b. Railroad Accident/Incident N/A			
3. Name of Railroad Responsible for Track Maintenance: Norfolk Southern Corp. [NS]			3a. Alphabetic Code NS			3b. Railroad Accident/Incident No. 23530			
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month Day Year 12 22 2005			6. Time of Accident/Incident 04:30: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM			
7. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision			4. Side collision 5. Raking collision 6. Broken Train collision			
			7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction			10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts			
			13. Other (describe in narrative)			01			
8. Cars Carrying HAZMAT 1		9. HAZMAT Cars Damaged/Derailed 1		10. Cars Releasing HAZMAT 0		11. People Evacuated 0		12. Division Georgia	
13. Nearest City/Town Crawford			14. Milepost (to nearest tenth) M227.8		15. State Abbr Code N/A GA		16. County PEACH		
17. Temperature (F) (specify if minus) 58 F		18. Visibility (single entry) 1. Dawn 3. Dusk 2. Day 4. Dark		Code 2		19. Weather (single entry) 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow		Code 1	
20. Type of Track 1. Main 3. Siding 2. Yard 4. Industry			Code 1						
21. Track Name/Number Single Main			22. FRA Track Code Class (1-9, X) 3		23. Annual Track Density (gross tons in millions) 12.9		24. Time Table Direction 1. North 3. East Code 1		
OPERATING TRAIN #1									
25. Type of Equipment Consist (single entry)			1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car			A. Spec. MoW Equip. Code 1		26. Was Equipment Attended? 1. Yes 2. No 1	
27. Train Number/Symbol 198G620									
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 34 MPH R			30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits			30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remotely controlled transmitter 0			
29. Trailing Tons (gross tonnage, excluding power units) 9477									
31. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded (yes/no)	32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.				
(1) First involved (derailed, struck, etc)		N/A	35	yes	Alcohol		Drugs		
(2) Causing (if mechanical cause reported)		0	0	N/A	0		0		
33. Was this consist transporting passengers? (Y/N)					N/A				
34. Locomotive Units		a. Head End	b. Mid Train	c. Rear End	35. Cars		a. Freight	b. Pass.	c. Empty
		d. Manual	e. Remote				d. Freight	d. Pass.	e. Caboose
(1) Total in Train		3	0	0	(1) Total in Equipment Consist		64	0	62
(2) Total Derailed		0	0	0	(2) Total Derailed		11	0	14
36. Equipment Damage This Consist		390100	37. Track, Signal, Way, & Structure Damage 18000		38. Primary Cause Code T220		39. Contributing Cause Code N/A		
Number of Crew Members					Length of Time on Duty				
40. Engineer/Operators 1		41. Firemen 0	42. Conductors 1	43. Brakemen 0	44. Engineer/Operator Hrs 3 Mi 0			45. Conductor Hrs 3 Mi 0	
Casualties to:		46. Railroad Employees	47. Train Passengers	48. Other	49. EOT Device? 1. Yes 2. No 1		50. Was EOT Device Properly Armed? 1. Yes 2. No 1		
Fatal		0	0	0	51. Caboose Occupied by Crew? 1. Yes 2. No		N/A		
Nonfatal		N/A	0	0					
OPERATING TRAIN #2									
52. Type of Equipment Consist (single entry)			1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car			A. Spec. MoW Equip. Code N/A		53. Was Equipment Attended? 1. Yes 2. No N/A	54. Train Number/Symbol N/A
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A			57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable			

56. Trailing Tons (<i>gross tonnage, excluding power units</i>)		N/A		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (<i>Specify in narrative</i>) Code(s)		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		N/A					
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.				Alcohol		Drugs			
(1) First involved (<i>derailed, struck, etc</i>)		0		N/A		N/A						N/A		N/A			
(2) Causing (<i>if mechanical cause reported</i>)		0		N/A		N/A		60. Was this consist transporting passengers? (Y/N)				N/A					
61. Locomotive Units		a. Head End		Mid Train		Rear End		62. Cars		Loaded		Empty		e. Caboose			
				b. Manual		c. Remote				a. Freight		b. Pass.		c. Freight		d. Pass.	
(1) Total in Train		0		0		0		(1) Total in Equipment Consist		0		0		0		0	
(2) Total Derailed		0		0		0		(2) Total Derailed		0		0		0		0	
63. Equipment Damage		This Consist		64. Track, Signal, Way, & Structure Damage		0		65. Primary Cause Code		N/A		66. Contributing Cause Code		N/A			
Number of Crew Members				Length of Time on Duty													
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator		72. Conductor							
N/A		N/A		N/A		N/A		Hrs 0 Mi 0		Hrs 0 Mi 0							
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		77. Was EOT Device Properly Armed?							
Fatal		0		0		0		1. Yes 2. No N/A		1. Yes 2. No N/A							
Nonfatal		0		0		0		78. Caboose Occupied by Crew?								N/A	
								1. Yes 2. No									
Highway User Involved				Rail Equipment Involved													
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle		Code		83. Equipment		3. Train (<i>standing</i>)		6. Light Loco(s) (<i>moving</i>)		Code					
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian				N/A		1. Train(<i>units pulling</i>)		4. Car(s)(<i>moving</i>)		7. Light(s) (<i>standing</i>)		N/A					
B. Truck E. Van H. Motorcycle M. Other (<i>spec. in narrative</i>)				N/A		2. Train(<i>units pushing</i>)		5. Car(s)(<i>standing</i>)		8. Other (<i>specify in narrative</i>)		N/A					
80. Vehicle Speed		N/A		81. Direction <i>geographical</i>		Code		84. Position of Car Unit in Train		N/A							
<i>(est. MPH at impact)</i>				1. North 2. South 3. East 4. West		N/A											
82. Position				Code		85. Circumstance		Code									
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				N/A		1. Rail Equipment Struck Highway User		N/A									
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?				Code		86b. Was there a hazardous materials release by		Code									
1. Highway User 2. Rail Equipment 3. Both 4. Neither				N/A		1. Highway User 2. Rail Equipment 3. Both 4. Neither		N/A									
86c. State here the name and quantity of the hazardous materials released, if any.														N/A			
87. Type of Crossing		1. Gates		4. Wig Wags		7. Crossbucks		10. Flagged by crew		88. Signaled Crossing Warning		Code		89. Whistle Ban		Code	
Warning		2. Cantilever FLS		5. Hwy. traffic signals		8. Stop signs		11. Other (<i>spec. in narr.</i>)		<i>(See instructions for codes)</i>		1. Yes		2. No		3. Unknown	
3. Standard FLS		6. Audible		9. Watchman		12. None				N/A		N/A		N/A		N/A	
Code(s)		N/A		N/A		N/A		N/A		N/A		N/A		N/A		N/A	
90. Location of Warning		Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code							
1. Both Sides				1. Yes		N/A		1. Yes		N/A							
2. Side of Vehicle Approach				2. No				2. No									
3. Opposite Side of Vehicle Approach		N/A		3. Unknown				3. Unknown									
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code					
N/A		1. Male		N/A		1. Yes 2. No 3. Unknown		N/A		1. Drove around or thru the Gate		4. Stopped on Crossing					
		2. Female								2. Stopped and then Proceeded		5. Other (<i>specify in narrative</i>)		N/A		N/A	
										3. Did not Stop							
97. Driver Passed Standing Highway Vehicle		Code		98. View of Track Obscured by (<i>primary obstruction</i>)		Code											
1. Yes 2. No 3. Unknown		N/A		1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (<i>specify in narrative</i>)		N/A											
				2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed													
101. Casualties to Highway-Rail Crossing Users		Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code					
		N/A		N/A		1. Killed 2. Injured 3. Uninjured		N/A		1. Yes		2. No		N/A		N/A	
						102. Highway Vehicle Property Damage (<i>est. dollar damage</i>)		N/A		103. Total Number of Highway-Rail Crossing Users (<i>include driver</i>)		N/A					
104. Locomotive Auxiliary Lights?						Code		105. Locomotive Auxiliary Lights Operational?		Code							
1. Yes 2. No						N/A		1. Yes 2. No		N/A							
106. Locomotive Headlight Illuminated?						Code		107. Locomotive Audible Warning Sounded?		Code							
1. Yes 2. No						N/A		1. Yes 2. No		N/A							

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.
HQ-108-2005
sketch.jpg



109. SYNOPSIS OF THE ACCIDENT

On December 22, 2005, the train crew for Norfolk Southern (NS) northbound Train 198G620 reported for duty at NS Columbus Yard, in Columbus, Georgia (GA) at 1:30 p.m., Eastern Standard Time (EST). The crew consisted of a conductor and locomotive engineer. The train consisted of three locomotives, NS 6628, NS 5344 and KCS 7015, and 126 cars of which 21 contained hazardous material. The train weighed 9,477 tons and was 7,124 feet in length.

About 4:30 p.m., Train 198G620 was operating at 34 miles per hour (mph) on the Columbus District single main track. Near milepost (MP) M228 they felt the slack run in, then adjust at MP M227.5, then the crew experienced an undesired emergency application of the train air brakes. After the train stopped, the conductor walked back 18 cars and observed the train had broken a knuckle on the 18th car. He asked the engineer to throw off a knuckle and pull ahead 18 car lengths. The conductor mounted the last car and told the engineer to shove back ten car lengths. At MP M227.3 he could see the rear portion of the train and instructed the engineer to stop. He observed the 22nd through the 46th cars had derailed. The first derailed car was KCS 751332 a load containing pulp-board. A loaded Liquid Carbon Dioxide hazardous material car, GATX 27403 tank car, was one of the 25 derailed cars, but was not leaking.

Track damage is \$18,000, equipment damage is \$390,100. There were no injuries or hazardous material spilled. The temperature was 58 F with clear visibility.

The cause of the derailment was a broken rail(transverse/compound fissure).

110. NARRATIVE

The following information was obtained from an investigation that was conducted by the FRA.

Circumstances Prior To The Accident

On December 22, 2005, at 1:30 p.m., an NS train crew reported for duty at Columbus Yard in Columbus, GA. The two employees, an engineer and conductor, were assigned to operate Northbound freight Train 198G620 from Columbus Yard in Columbus to Brosnan Yard, in Macon, GA. The train consisted of three locomotives, NS 6628, NS 5344, and KCS 7015, 126 cars, 64 loads and 62 empties, weighing 9,477 tons and 7,124 feet in length.

The crew had a job briefing and contacted the yardmaster for location of their train, which was on the main track at the north end of the yard. The engineer contacted the train dispatcher and copied track warrant 5096 authorizing Train 198G620 to operate from Newby MP (M287.0) to Columbus Jct. (M220.0) on the NS Columbus District, Georgia Division. They departed Columbus Yard at 2:08 p.m.

The engineer said the dynamic brakes were not working properly when they left Columbus Yard, therefore, he had to control the train speed using throttle modulation and the train air brakes. The engineer was sitting on the right side of the locomotive cab, and the conductor was sitting in the front seat on the left side of the locomotive cab. The train was traveling in a northward direction at 34 mph.

Approaching the derailment location, beginning at MP M230, the track is tangent, with 0.12-percent descending grade for a distance of 0.7 mile. At MP M229.7 begins a 1.5-degree left hand curve with a .07-percent descending grade. The next mile is tangent on a .07-percent descending grade. At MP M228.1 begins a 2.5-degree left hand curve, then a 2.7-degree right hand curve for 0.6 mile.

The railroad's timetable direction of this train is north. The geographic direction was northwest. Timetable directions are used throughout this report.

The Accident

The engineer said at MP M228.0 he felt the slack run in and adjust out when the locomotive reached MP M227.5. At this point the train traveling at 34 mph had an undesired emergency application of the train air brakes. The lead locomotive came to a stop at MP M227.3. The conductor looked back and could see an opening in his train. He walked toward the rear of his train and informed the engineer they had broken a knuckle. He asked the engineer to throw off a knuckle and pull ahead 18 cars. The conductor stopped the

movement at the knuckle, secured three step protection, and replaced the broken knuckle. He mounted the rear car, instructed the engineer to shove back ten car lengths, and observed the rear portion of his train, which had derailed. About 5 p.m. the conductor called the engineer via radio and told him to notify the train dispatcher that 25 cars had derailed on Train 198G620. After reviewing the train consist, he informed the dispatcher that one of the derailed cars contained hazardous material, Liquid Carbon Dioxide.

At 5:45 p.m. the train dispatcher notified the assistant superintendent of operations in Atlanta, GA, the assistant division engineer in Atlanta, the trainmaster at Americus, GA, and the roadmaster and mechanical superintendent at Macon about the derailment. They arrived at the accident site about 6:50 p.m. to determine the cause. Derailment repair crews from Hulcher and RJ Corman arrived at about 10 p.m. and began the accident clean up.

Analysis and Conclusion

These damages did not qualify for Post Accident Toxicological Testing under Subpart-C of 49 CFR, Part 219.201. However, NS officials made a good faith determination and tested the engineer and conductor. The tests were negative for both employees.

The maximum authorized speed on the Columbus District is 49 mph. At the point of derailment (POD), the speed is restricted to 35 mph. The download from the event recorder indicates that Train 198G620 reached a speed of 34 mph prior to the emergency application of the train air brakes. NS road foreman of engines reviewed the event recorder and determined that the engineer followed all train handling requirements.

NS is required to conduct operational tests and inspections on all train and engine service employees. A review of tests conducted on the locomotive engineer revealed that NS officials checked this individual for operating and safety rules compliance a total of 60 times between November 22, 2005 and December 22, 2005, with no failures recorded. The conductor was observed a total of 54 times with no failures recorded. The FRA conducted an inspection of NS track records, which included: the Sperry Rail Car Report dated August 9, 2005, track geometry car report dated September 14, 2005, and track inspections for the week of December 19, 2005 through December 23, 2005. After reviewing these records no defects were noted that were related to this accident.

An investigation of the derailment site was conducted by FRA and NS mechanical, engineering and transportation managers. At this location, the rail was 115 lbs welded rail rolled in December 1953 and installed in 1999 by NS Maintenance of Way. New wood crossties and track surfacing was completed in January 2005. At MP M227.8, the POD, investigators found a section of 115 lbs rail that was battered in the left hand curve on the high rail. An inspection of this rail-end indicated the rail contained an internal defect. This was shown by a dark area located on the bottom of the rail ball surrounded by a shiny, brightly colored break. The suspected pieces of broken west rail was cut out and sent to NS's laboratory for testing. NS tested the two pieces of rail and the test revealed the rail pieces had about 40% Transverse Defect. The Transverse Defect contained 30% normal growth and 10% rapid growth. The cause of the derailment of Train 198G620 was a Transverse/Compound Fissure.