



OFFICE OF RESEARCH & DEVELOPMENT

2012 R&D REVIEW

Rail Seat Abrasion



U.S. Department
of Transportation

Federal Railroad
Administration

HUGH THOMPSON
Program Manager

Office of Research and Development
Office of Railroad Policy and Development

NICK WILSON
TTCI

Program Area & Risk Matrix

Rail Seat Abrasion

Program Areas	Risk Factors	Trespass	Grade Crossing	Derailment	Train Collision	All Other Safety Hazards
Railroad Systems Issues						
Human Factors						
Track & Structures				X		
Track & Train Interaction						
Facilities & Equipment						
Rolling Stock & Components						
Hazardous Materials						
Train Occupant Protection						
Train Control & Communications						
Grade Crossings & Trespass						

Acknowledgements & Stakeholders

Acknowledgements

- Mike Coltman, Volpe
- Brian Marquis, Volpe
- John Choros, Volpe

Stakeholders & Project Partner(s)

- Mark Austin, CSX
- Seth Ogan, BNSF

Introduction

- Rail Seat Abrasion (RSA) is loss of material in the rail seat on concrete ties.
 - Loss of clip preload
 - Loss of proper rail cant
 - Gage widening



- Working Theory: Deep, wedge shaped abrasion can be caused by severe track geometry deviations. These deviations cause wheel rail forces that produce high stresses in the rail seat.


Objectives

- Phase I of the project had three main objectives:
 - Measure RSA at selected revenue service sites to determine severity and extent of RSA, depth and patterns of RSA, and track geometry.
 - Use the field measurements as input to NUCARS^{®1} simulations to determine track features and locations where vehicle performance was expected to introduce high lateral loads into the track.
 - Identify potential track geometry features for use in a future test zone on the Facility for Accelerated Service Testing (FAST) High Tonnage Loop to study RSA in a more controlled environment
- Concurrently, results were provided to the Federal Railroad Administration (FRA) and Volpe to support their efforts in developing RSA predictive modeling tools.

1. NUCARS[®] is a registered trademark of Transportation Technology Center, Inc.

Motivation for Project

- Home Valley, Washington, Derailment
- Sprague, Washington, Derailment
- "...attributed to excessive concrete crosstie abrasion, which allowed the outer rail to rotate outward and create a wide gage track condition."



Rosenker, Sumwalt, Hersman, Higgins. Railroad Accident Brief NTSB/RAB-06/03, National Transportation Safety Board, Washington D.C., 10/18/2006,

Method

- Work with Railroad partners to identify areas where rails would be removed from concrete ties for maintenance.
- Do a pre-inspection trip to survey the condition at the site and measure rail profiles.
- Obtain track geometry measurements from the site.
- Take measurements in coordination with the railroad maintenance work.
- Use track geometry to perform NUCARS® simulations of inspected sites.
- Correlate and plot simulation results together with the inspection results.

Method

- Field Survey Measurement Approach
 - RSA cannot be measured without removing the rail.



- For this reason measurements were performed during rail replacements and rail seat repairs.

Method - Measurements





- Rail was declipped, swung out of the way, and railroad personnel cleaned old pads off of the rail seat.
- When this was finished the rail seats could be measured.
- The team replacing pads followed only a short distance behind leaving a limited time for measurements.



Method - NUCARS[®] Simulations




- Track geometry from the railroads and from the FRA DOTX 218 Car was used as input to simulations
- Included a track model so the forces between the rail and tie could be examined
- Loaded 100 ton 4 axle freight car, base case assumed one wheel profile and dry rail ($\mu=0.4$)



Results – Measurement Summary

- Three sites were inspected, total of 16 curves
- The CSX site in West Virginia had the highest rainfall, the tightest curvature, and the most abrasion
- The BNSF sites in Needles California and Alliance Nebraska had low rainfall, low curvature, and little abrasion – one curve at Needles showed abrasion onset
- Where abrasion was found, the pattern followed the change in curvature
- No localized track geometry features were correlated to areas of higher abrasion
- The following slides show examples of the inspection and simulation data

Results: CSX – significant abrasion



- These 3 curves were measured with manual gage
- An automatic system used initially had much more scatter than manual gage
 - See first 208 ties of 19.7


Avg = Average of measurements taken on field and gage side of rail seat.

Difference = Average of measurements on the field side minus the average of measurements on the gage side of the rail seat.

Positive = rail rolled out.


Results – CSX MP16

- Sample results for the CSX site. Curve at MP16 on the Coal River Subdivision near St. Albans, WV
- Simulation L/V results generally match the pattern of abrasion
- No distinct peaks in track geometry, lateral force or abrasion to indicate localized geometry induced abrasion




Results - CSX Simulations

- Simulation data shows the load and moment between the rail and crosstie as the axles of a car pass over it.
- Negative forces indicate compression of the rail seat. Positive moments are toward the field side.
- These forces are for a tie in the entry spiral





Results – CSX Simulations

- These forces are for the exit spiral in the simulation.
- Note that at this location both axles of a truck cause positive moments on the rail seat.




Results – CSX Simulations

- Wheel-rail contact condition on axle 1
- Contact in the flange root and a second point of contact at the flange tip.




Results – CSX Simulations

- Wheel-rail contact condition on axle 2
- Contact is only in the flange root.
- The location of the contact points affects the moment transferred to the rail seat.



Results: Needles- very little abrasion




Avg = Average of measurements taken on field and gage side of rail seat.

Difference = Average of measurements on the field side minus the average of measurements on the gage side of the rail seat.

Positive = rail rolled out.

Results – BNSF Needles MP584


- Sample results for the only BNSF site with significant abrasion. Curve at MP584 near Needles.
- Simulation L/V results much lower than CSX but generally match the pattern of abrasion
- No distinct peaks in track geometry, lateral force or abrasion to indicate localized geometry induced abrasion



Results – BNSF MP584 Simulations

Effect of speed on rail seat forces

- East and west bound traffic at site have two distinct operational speeds at site:
 - Red = 50 mph
 - Blue = 15 mph
- Simulation is for 4-axle 100 ton loaded freight car. General traffic at site is mixed, including large amount of intermodal multi-platform cars, with smaller amount of heavy haul.



Axle 1 Axle 2

Axle 3 Axle 4

Results – BNSF MP584 Simulations

Effect of W/R friction on simulation results


Evidence of lubrication found at site. However friction coefficient and type of lubricant was not measured.

Green = dry rails

Red = gauge face lubrication

Blue = TOR friction modifier

Purple = Gauge face lubrication and TOR friction modifier



Conclusions from Phase I

- Sixteen curves on three different railroads were inspected and analyzed for Rail Seat Abrasion (RSA)
 - Where RSA was found, the severity appeared to be generally related to track curvature
- Simulation results generally match the rail seat abrasion patterns that were measured
- Local traffic, operational and lubrication practices can affect results
 - May need to simulate local conditions in greater detail

Conclusions from Phase I, continued

- A hypothesis that a particular track geometry feature (such as down and out perturbations) is a trigger for the development of RSA could not be confirmed from the limited number of sites where RSA was found
- Measurement methods probably affected this result
 - Access was limited to where track work was being done
 - Need accurate automated tools to speed up measurements and avoid skipping ties
 - Need to measure wheel and rail profiles
 - Need to measure rail friction conditions
 - Need to measure pad and clip details
 - Need space curve track geometry for model input

Proposed Phase II Work

- Use a previously measured down and out perturbation as a starting point, use modeling to identify a track geometry deviation expected to cause Rail Seat Abrasion
- Install this perturbation at FAST where it can be carefully monitored
 - Gage, crosslevel, rail cant, gage restraint with the LTLF, wayside forces, and instrumented freight car